# Attachment C

This page intentionally left blank.

			Change, O	ther='s M	e, FC='s Field iscellaneous s Error and/or n
					ge Order
Funding Impact/Status	Change Order	Short Description	СО Туре	Amt	
1. Original Contingency Budget	CO #001	Storm Drain Modification	SC	\$	26,598
	CO #002	Relocate gas line	E & O	\$	2,116
	CO #003	Hazardous Material Removal	FC	\$	6,750
	CO #004	Move existing County containers from project site	SC	\$	1,487
	CO #005	Credit for reduced bike rack requirement	SC	\$	(2,421)
	CO #006	Add baby changing stations	E & O	\$	3,344
	CO #007	Add gas line shutoff	E & O	\$	5,815
		Concrete Masonry Unit wall modifications for			
	CO #008	plumbing	E & O	\$	1,744
	CO #009	Additional work due to unknown ground conditions	FC	\$	112,559
		Remove and reroute existing concrete encase electrica			
	CO #010	conduits	FC	\$	21,333
	CO #011	Relocate existing fiber optic lines	FC	\$	12,837
	CO #012	Demo existing concrete culverts	FC	\$	4,011
	CO #013	Building beam modifications	E&O	\$	23,912
	CO #014	Plumbing repair at Construction Manager Office	SC	\$	290
	CO #015	Added rebar to 4" walls	E & O	\$	1,335
		Site portable toilets, wash stations, water - water		<u>,</u>	2 000
	CO #016	shutdown	FC	\$	3,800
	CO #017	Replace existing fire hydrant	FC	\$	3,756
	CO #018	Unknown plumbing work under concrate slab	E & O	\$	590,000
	00 11040		50	<u> </u>	005 000
	CO #019	Additional work due to unknown ground conditions	FC	\$	935,000
	CO #020	Added power to lighting control panel	E&O	\$	1,916
	CO #021	Add steel column at Building 4	SC	\$	8,943
	CO #022	Revise electrical conduit	SC	\$	(22,310)
	CO #023	Storm drain at Building 7	E&O	\$	7,172
	CO #024 CO #025	Added circuit breater to Building 2	E & O FC	\$	2,180
		Drilling for low voltage	E&O	\$	5,082 15,439
	CO #026 CO #027	Lower windows at Building 1B	E&O	\$	,
		Lower windows at Building 1B		\$	6,447
	CO #028 CO #029	Added steel column to Building 6	E & O E & O	\$ \$	8,943
		Added power line			6,815
	CO #030	Lower fire water line Reset 6" sewer line	FC FC	\$ \$	17,675
	CO #031 CO #032	Exterior wall access door modification	E&O		3,138 7,067
	CO #032	Additional welding in Building 7	FC	\$ \$	638
	CO #033 CO #034	Additional weiging in Building 7 Added fasteners for masonry work	E&O	\$ \$	1,232
	CO #034	Extend Building 4 beams	E&O	\$ \$	2,242
	CO #035	Lower existing water line	FC	\$ \$	40,476
	CO #038	Increase Building 1A exhause fan	E&O	\$ \$	2,008
	CO #037	Replace existing sewer lines	FC	\$ \$	33,113
	CO #038	Added circuit breater to Building 4	E&O	\$ \$	2,240
	CO #039 CO #040	Added circuit breaker to Building 4 Added circuit breaker to Building 1A	E&O	\$ \$	2,240
	CO #040 CO #041	Added circuit breater to Building 1A	E&O	\$ \$	1,945
	CO #041 CO #042	Added circuit breater to Building 5 Added circuit breater to Building 6	E&O	ې \$	1,050
	CO #042	Added circuit breater to Building 6	E&O	\$ \$	1,795
	CO #043 CO #044		FC	\$ \$	26,441
	CO #044 CO #045	Added conduit supports in Building 7 Added circuit breater to Building 4	E&O	\$ \$	3,861
		-			
	CO #046	Added power/data to Building 7	E&O	\$	3,382
	CO #047	Revise power pathway	E & O	\$ ¢	125,207
	CO #048 CO #049	Revise shower partitions Low voltage tie-in	Other E & O	\$ \$	50,124 21,549
	CO #049	Low Voltage LIE-III	LQU	ې	21,549

1. Original Contingency Budget	CO #050	Added beams in Building 2	E & O	\$	2,151
	CO #051	Added detention window frames	E & O	\$	5,348
	CO #052	Added manhole	SC	\$	61,301
	CO #053	ADA modifications in Buildings 1A/1B and 2	E & O	\$	20,664
	CO #054	Lintel ledger coordination work	E & O	\$	1,070
	CO #055	Added footing and column on Building 4	E & O	\$	9,594
	CO #056	Additional cameras in Building 7	SC	\$	12,547
	CO #057	Missing circuits for Building 4 HVAC	E & O	\$	11,194
	CO #058	Added drop ceilings in Building 1B	E & O	\$	3,621
	CO #059	Revised exterior light near lobby	E & O	\$	1,644
	CO #061	Sewer system excavation	FC	\$	5,349
	CO #062	Revised privacy partitions in Building 4	E & O	\$	9,609
	CO #063	Revised light fixtures	E & O	\$	3,623
	CO #064	Revised door frames in Buildings 1A/1B	E & O	\$	49,841
	00 4005	Remove coat hooks and lower cameras throughout	5 9 0	÷	4 007
	CO #065	buildings	E&O	\$	1,037
	CO #066	Revise security device heights	E & O	\$	2,147
	CO #067	Reroute water line	FC	\$	7,245
		Additional labor and materials for revised door frames			
	CO #068	in Buildings 1A/1B	E & O	\$	141,233
	CO #069	Revised windows in Building 2	E & O	\$	88,611
	CO #070	Revised window glazing on non-detention frames	E & O	\$	53,662
	CO #071	Revised mechanical system roof access	E & O	\$	119,478
	CO #072	Revised mechanical system roof access	E & O	\$	98,565
	CO #073	Added room signage	SC	\$	12,781
		Revisions to detention doors and windows in Buildings			
	CO #074	4, 5 and 6	E & O	\$	78,640
	CO #075	Revised mechanical system roof access	E & O	\$	84,527
	CO #076	Extended fire water line tie in	FC	\$	5,386
	CO #077	French Drain at Natividad CMU Wall	FC	\$	1,449
	CO #078	Added electrical work in Building 4	E & O	\$	7,293
	CO #079	Credit for fascia boards	SC	\$	(5,825)
	CO #080	Non-Detention Keying changes	SC	\$	44,065
	CO #081	Furniture, Fixture and Equipment Additions	E & O	\$	9,656
	CO #082	Added Intumescent Paint for three columns	E & O	\$	12,678
	CO #083	Added bed anchors at Header Board Frames	E & O	\$	14,092
	CO #084	Revisions to Building 4 pharmacy	SC	\$	10,172
	CO #085	Anti-Graffiti Coating	SC	\$	14,659
	CO #086	No-Climb Fence fabric	SC	\$	17,074
	CO #087	Revisions to Locker Room	E & O	\$	13,847
	CO #088	Added plumbing in Building 7	FC	\$	5,175
	CO #089	Revised bed design in Building 7	SC	\$	36,362
	CO #090	Replace electrical power feeders in Building 7	FC	\$	13,292
	CO #001	Repair and servicing of existing 12kV and 5kV	EC	ć	AE 174
	CO #091 CO #092	Switchgear Delete all HVAC condensate line piping insulation	FC SC	\$ \$	45,174
	CO #092	Delete all HVAC condensate line piping insulation	SC	Ş	(3,010)
	CO #003	Mabilization for alastrical utility shutdows 12/15/2010	EC	ć	14 204
	CO #093	Mobilization for electrical utility shutdown 12/15/2018		\$	14,304
	CO #094	Add sink, plumbing, countertop	SC	\$	7,539
	CO #095	Revised classroom ceiling in Buildings 2 and 6	E&O	\$	84,594
	CO #096	Revisions to site security fence.	SC	\$	83,993
	CO #097	Revised window glazing in Buildings 1A/1B and 2	E&O	\$	13,239
	CO #098	Furniture design revisions	SC	\$	28,992
	CO #099	Negotiated resolution for Contractor claiim.	Other	\$	-
	CO #100	Revise door hardware in Building 4	E&O	\$	2,547
	CO #101	Relocate youth telephones in Buildings 1A/1B	E&O	\$	12,476
	CO #102	Replace existing sewer pipe in Building 7	FC	\$	7,702
	CO #103	Install drywall cover pipe conduit Bldg 7	FC	\$	4,409
		Revised fire sprinkler system in Building 4 lobby,			
	CO #104	visitation	SC	\$	61,220

		Revised fire sprinkler system in Building 4 rooms 152			
1. Original Contingency Budget	CO #105	and 163	SC	\$	11,819
	CO #106	Credit: Revised mechanical system roof access	SC	\$	(82,637)
	CO #107	Credit for lack of circuit breaker	E & O	\$	(1,252)
	CO #108	Added detention grade glass in Buildings 4, 5, and 6	E & O	\$	192,728
	CO #109	Revisions to Building 4 corridors	SC	\$	18,114
	CO #110	Revised countertop heights throughout facility	SC	\$	41,494
	CO #111	Revised bed design in Building 7	SC	\$	23,824
	CO #112	Fire water check valve	FC	\$	149,645
		Revise each Gym Overhead Coiling Door to include a			,
		manual			
	CO #113	operator with a removable crank.	SC	\$	7,531
	CO #114	Raise bottom of doors to 8" above slab elevation.	FC	\$	4,409
		Rooms 159 & 160 – Add special coatings SC-1 and SC-2			
	CO #115	in the shower areas.	E & O	\$	9,422
		Add Acoustical Tile Ceilings in Rooms 108, 117, 131,			
	CO #116	132, 135	SC	\$	45,000
	CO #117	Add Flooring at Officer Stations and add Podiums	SC	\$	5,419
	CO #118	Add Steel Sill Plates at Coiling Doors	E&O	\$	4,876
	CO #119	Provide and install three additional access doors	Other	\$	1,232
		RM 115 – Provide and install Stainless Steel Posts for			,
		Toilet			
	CO #120	Partitions	Other	\$	3,893
		RM 101, 148, 149 – Delete SC-1 Coating from floor and			
		add			
	CO #121	replace with Concrete Sealer	SC	\$	(1,136)
		RM 115 & 117– Provide and install recessed DTTD in			
	CO #122	compliance with ADA Standards.	E & O	\$	2,165
	CO #123	Add SC-2 Floor Coating System.	SC	\$	1,050
	CO #124	Added double check valves	FC	\$	54,091
	CO #125	Revisions to volume damper controls	Other	\$	66,611
	CO #126	Added back draft dampers	Other	\$	20,906
	CO #127	Rooms 131 & 132 – Delete card reader devices.	SC	\$	(3,091)
		Room 106 – Delete all data and power outlets.			
	CO #128	REFERENCE SE1.7.1 &E2.7.1	SC	\$	(9,061)
		Install Exterior Lighting Control circuits from LP-7-A-15			
	CO #129	via lighting control panel LCP-7	E & O	\$	3,677
		Revise Bed Layout and add bed headerboard (Includes			
	CO #130	the addition of a finished wood cap on wall)	SC	\$	13,500
		Install additional duplex GFCI outlet in the Staff			
	CO #131	restrooms	E & O	\$	5,009
		Install detention toilet paper holder in the Youth			
	CO #1 22	restrooms and sleeping rooms.	E & O	\$	9,034
	CO #132				
	CU #132	Install flush control valves for detention plumbing			
	CO #132	Install flush control valves for detention plumbing	SC	\$	66,432
				\$	66,432
		Install flush control valves for detention plumbing fixtures in Buildings 1A/1B		\$ \$	66,432
	CO #139	Install flush control valves for detention plumbing fixtures in Buildings 1A/1B Remove the existing sealant at all exterior vertical	SC		66,432 - (7,253)
	CO #139 CO #155	Install flush control valves for detention plumbing fixtures in Buildings 1A/1B Remove the existing sealant at all exterior vertical masonry joints and replace with Security Sealant.	sc sc	\$ \$	-
	CO #139 CO #155 CO #199	Install flush control valves for detention plumbing fixtures in Buildings 1A/1B Remove the existing sealant at all exterior vertical masonry joints and replace with Security Sealant. Credit for revised bioswale work	SC SC SC	\$ \$ \$	- (7,253)
. Original Contingency Budget Total	CO #139 CO #155 CO #199 CO #202 CO #203	Install flush control valves for detention plumbing fixtures in Buildings 1A/1B Remove the existing sealant at all exterior vertical masonry joints and replace with Security Sealant. Credit for revised bioswale work Add detention grade privacy curtains	SC SC SC TBD	\$ \$	- (7,253) 1,019 5,977
	CO #139 CO #155 CO #199 CO #202 CO #203	Install flush control valves for detention plumbing fixtures in Buildings 1A/1B Remove the existing sealant at all exterior vertical masonry joints and replace with Security Sealant. Credit for revised bioswale work Add detention grade privacy curtains	SC SC SC TBD	\$ \$ \$ <b>\$</b>	- (7,253) 1,019 5,977 <b>4,254,880</b>
. Original Contingency Budget Total 2. BOS Approval 2019-06-25	CO #139 CO #155 CO #199 CO #202 CO #203	Install flush control valves for detention plumbing fixtures in Buildings 1A/1B Remove the existing sealant at all exterior vertical masonry joints and replace with Security Sealant. Credit for revised bioswale work Add detention grade privacy curtains Revised window design due to fire rating Revision to Cell Diffuser Grilles	SC SC SC TBD E & O Other	\$ \$ \$ <b>\$</b> \$	(7,253) 1,019 5,977 <b>4,254,880</b> 24,524
	CO #139 CO #155 CO #199 CO #202 CO #203	Install flush control valves for detention plumbing fixtures in Buildings 1A/1B Remove the existing sealant at all exterior vertical masonry joints and replace with Security Sealant. Credit for revised bioswale work Add detention grade privacy curtains Revised window design due to fire rating Revision to Cell Diffuser Grilles Remove unstable soil from staff parking lot	SC SC TBD E & O	\$ \$ \$ <b>\$</b>	- (7,253) 1,019 5,977 <b>4,254,880</b>
. Original Contingency Budget Total 2. BOS Approval 2019-06-25	CO #139 CO #155 CO #199 CO #202 CO #203	Install flush control valves for detention plumbing fixtures in Buildings 1A/1B Remove the existing sealant at all exterior vertical masonry joints and replace with Security Sealant. Credit for revised bioswale work Add detention grade privacy curtains Revised window design due to fire rating Revision to Cell Diffuser Grilles	SC SC SC TBD E & O Other	\$ \$ \$ <b>\$</b> \$	(7,253) 1,019 5,977 <b>4,254,880</b> 24,524

		Gym -Provide electrical raceway only for Owner			
2. BOS Approval 2019-06-25	CO #138	Provided Wireless Access equipment at two locations.	SC	\$	922
2. 505 Approval 2015 00 25	CO #140	Provide nightstands adjacent to beds.	SC	\$	23,816
	CO #141	Add return air ductwork and register.	E & O	\$	5,129
	CO #142	Install sewer cleanout hooks	SC	\$	18,655
	CO #144	Revise ADA toilet seats	E & O	\$	8,050
	CO #145	Revise security fence to add anti-climb man-gates	SC	\$	3,456
2. BOS Approval 2019-06-25 Total	0 1145	nevise security rence to dud unti climb man gates	50	\$	102,887
2. BOS Approval 2019-07-23	CO #134	Phase 1 - Glazing Installation costs Only.	Other	\$	149,863
	CO #135	Phase 1 - Add Interior Glazing Stops to Frames.	Other	\$	149,861
	CO #143	Replace faucets with anti-ligature bubblers	E & O	\$	4,434
	00 1140	Revise wall to full height to bottom of roof in Building	Luo	Ŷ	-,-5-
	CO #146	4	Other	\$	4,500
	CO #147	Revise accessdoor size	Other	\$	2,358
	CO #148	Delete angle iron requirement at storefront doors	SC	\$	(321)
	00 112 10	Install concertina coil barbed wire around youth	50	Ŷ	(321)
	CO #149	housing rec yards	SC	\$	38,349
	CO #150	Add fire alarm tamper switches	Other	\$	27,305
	CO #150	Add data jacks throughout classroom	E & O	\$	8,120
	CO #151	Revisions to razor wire between buildings	SC	\$	7,745
		Floor preparation for installation of clear concrete	30	Ļ	7,743
	CO #153	sealer.	Other	\$	4,094
	CO #133	Furnish and install concrete bases to mount the	other	Ļ	+,034
	CO #154	lockers.	Other	\$	9,211
	CO #154	Add securoty exhaust grills in all youth restrooms	Other	\$	7,900
	CO #150	Add fire retardant to officer work stations	SC	\$	11,230
	CO #130	Add me retardant to omeer work stations	50	Ļ	11,230
	CO #161	Add epoxy floor coating to rooms in Buildings 1A/1B	SC	\$	103,685
	CO #205	Add polished floors in Building 6	SC	\$	46,919
2. BOS Approval 2019-07-23 Total	0 1205		50	\$	575,252
	CO #157	Add corner guards to officer work stations	SC		
2. BOS Approval 2019-11-05	CO #157 CO #159	Add corner guards to officer work stations Revisions to peremiter security fences	SC SC	\$	4,561
	CO #159	Revisions to peremiter security fences	SC	\$ \$	4,561 4,575
	CO #159 CO #160	Revisions to peremiter security fences Add condensate drain line	SC Other	\$ \$ \$	4,561 4,575 1,448
	CO #159 CO #160 CO #162	Revisions to peremiter security fences Add condensate drain line Revise light fixtures to high security recessed lights	SC Other Other	\$ \$ \$ \$	4,561 4,575 1,448 10,294
	CO #159 CO #160 CO #162 CO #163	Revisions to peremiter security fences Add condensate drain line Revise light fixtures to high security recessed lights Revised sink designs	SC Other Other E & O	\$ \$ \$ \$	4,561 4,575 1,448 10,294 532
	CO #159 CO #160 CO #162 CO #163 CO #164	Revisions to peremiter security fences Add condensate drain line Revise light fixtures to high security recessed lights Revised sink designs Relocate soap dispensers per ADA	SC Other Other E & O Other	\$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165	Revisions to peremiter security fences Add condensate drain line Revise light fixtures to high security recessed lights Revised sink designs Relocate soap dispensers per ADA Extend HVAC duct work	SC Other Other E & O Other FC	\$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165 CO #166	Revisions to peremiter security fences Add condensate drain line Revise light fixtures to high security recessed lights Revised sink designs Relocate soap dispensers per ADA Extend HVAC duct work Revised door lever design	SC Other Other E & O Other FC E & O	\$ \$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364 274
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165 CO #166 CO #167	Revisions to peremiter security fences Add condensate drain line Revise light fixtures to high security recessed lights Revised sink designs Relocate soap dispensers per ADA Extend HVAC duct work Revised door lever design Add stainless steel toekick plates in Building 4	SC Other Other E & O Other FC E & O SC	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364 274 2,774
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165 CO #166	Revisions to peremiter security fences Add condensate drain line Revise light fixtures to high security recessed lights Revised sink designs Relocate soap dispensers per ADA Extend HVAC duct work Revised door lever design Add stainless steel toekick plates in Building 4 Replace padlocks in Building 4 lockers	SC Other Other E & O Other FC E & O	\$ \$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364 274
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165 CO #166 CO #167 CO #168	Revisions to peremiter security fencesAdd condensate drain lineRevise light fixtures to high security recessed lightsRevised sink designsRelocate soap dispensers per ADAExtend HVAC duct workRevised door lever designAdd stainless steel toekick plates in Building 4Replace padlocks in Building 4 lockersReshape bioswale to accomidate exterior fence	SC Other Cher E & O Other FC E & O SC SC	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364 274 2,774 1,395
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165 CO #166 CO #167 CO #168	Revisions to peremiter security fences Add condensate drain line Revise light fixtures to high security recessed lights Revised sink designs Relocate soap dispensers per ADA Extend HVAC duct work Revised door lever design Add stainless steel toekick plates in Building 4 Replace padlocks in Building 4 lockers Reshape bioswale to accomidate exterior fence pathway	SC Other E & O Other FC E & O SC SC SC	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364 274 2,774 1,395 32,447
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165 CO #166 CO #167 CO #168 CO #169 CO #170	Revisions to peremiter security fencesAdd condensate drain lineRevise light fixtures to high security recessed lightsRevised sink designsRelocate soap dispensers per ADAExtend HVAC duct workRevised door lever designAdd stainless steel toekick plates in Building 4Replace padlocks in Building 4 lockersReshape bioswale to accomidate exterior fencepathwayRevised door hardware	SC Other Other E & O Other FC E & O SC SC E & O	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364 2,74 2,774 1,395 32,447 497
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165 CO #166 CO #167 CO #168 CO #169 CO #170 CO #171	Revisions to peremiter security fencesAdd condensate drain lineRevise light fixtures to high security recessed lightsRevised sink designsRelocate soap dispensers per ADAExtend HVAC duct workRevised door lever designAdd stainless steel toekick plates in Building 4Replace padlocks in Building 4 lockersReshape bioswale to accomidate exterior fencepathwayRevised door hardwareCSFM field inspection revisions	SC Other E & O Other FC E & O SC SC SC E & O FC	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364 274 2,774 1,395 32,447 497 36,268
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165 CO #166 CO #167 CO #168 CO #169 CO #170 CO #171 CO #172	Revisions to peremiter security fencesAdd condensate drain lineRevise light fixtures to high security recessed lightsRevised sink designsRelocate soap dispensers per ADAExtend HVAC duct workRevised door lever designAdd stainless steel toekick plates in Building 4Replace padlocks in Building 4 lockersReshape bioswale to accomidate exterior fencepathwayRevised door hardwareCSFM field inspection revisionsRevised pathway to provide electrical room access	SC Other E & O Other FC E & O SC SC SC SC FC SC	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364 274 2,774 1,395 32,447 497 36,268 5,696
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165 CO #166 CO #167 CO #168 CO #169 CO #170 CO #171	Revisions to peremiter security fencesAdd condensate drain lineRevise light fixtures to high security recessed lightsRevised sink designsRelocate soap dispensers per ADAExtend HVAC duct workRevised door lever designAdd stainless steel toekick plates in Building 4Replace padlocks in Building 4 lockersReshape bioswale to accomidate exterior fencepathwayRevised door hardwareCSFM field inspection revisions	SC Other E & O Other FC E & O SC SC SC E & O FC	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364 274 2,774 1,395 32,447 497 36,268
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165 CO #166 CO #167 CO #168 CO #169 CO #170 CO #171 CO #172 CO #173	Revisions to peremiter security fences Add condensate drain line Revise light fixtures to high security recessed lights Revised sink designs Relocate soap dispensers per ADA Extend HVAC duct work Revised door lever design Add stainless steel toekick plates in Building 4 Replace padlocks in Building 4 lockers Reshape bioswale to accomidate exterior fence pathway Revised door hardware CSFM field inspection revisions Revised pathway to provide electrical room access Add metal stud frame wall in Building 4	SC Other E & O Other FC E & O SC SC SC SC SC SC SC SC SC Other	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364 274 2,774 1,395 32,447 497 36,268 5,696 2,834
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165 CO #166 CO #167 CO #168 CO #169 CO #170 CO #171 CO #172 CO #173	Revisions to peremiter security fences Add condensate drain line Revise light fixtures to high security recessed lights Revised sink designs Relocate soap dispensers per ADA Extend HVAC duct work Revised door lever design Add stainless steel toekick plates in Building 4 Replace padlocks in Building 4 lockers Reshape bioswale to accomidate exterior fence pathway Revised door hardware CSFM field inspection revisions Revised pathway to provide electrical room access Add metal stud frame wall in Building 4 Revise door escurity glazing and hardware in Building 7	SC Other E & O Other FC E & O SC SC SC SC SC SC SC SC SC Other	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364 274 2,774 1,395 32,447 497 36,268 5,696 2,834
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165 CO #166 CO #167 CO #168 CO #169 CO #170 CO #171 CO #172 CO #173 CO #174 CO #175	Revisions to peremiter security fences Add condensate drain line Revise light fixtures to high security recessed lights Revised sink designs Relocate soap dispensers per ADA Extend HVAC duct work Revised door lever design Add stainless steel toekick plates in Building 4 Replace padlocks in Building 4 lockers Reshape bioswale to accomidate exterior fence pathway Revised door hardware CSFM field inspection revisions Revised pathway to provide electrical room access Add metal stud frame wall in Building 4 Revise door escurity glazing and hardware in Building 7 Change exterior wall paint color	SC Other   E & O Other   FC E & O SC SC SC SC SC SC SC SC SC Other   SC	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364 2,774 1,395 32,447 497 36,268 5,696 2,834 10,237 7,444
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165 CO #166 CO #167 CO #168 CO #169 CO #170 CO #171 CO #172 CO #173	Revisions to peremiter security fences Add condensate drain line Revise light fixtures to high security recessed lights Revised sink designs Relocate soap dispensers per ADA Extend HVAC duct work Revised door lever design Add stainless steel toekick plates in Building 4 Replace padlocks in Building 4 lockers Reshape bioswale to accomidate exterior fence pathway Revised door hardware CSFM field inspection revisions Revised pathway to provide electrical room access Add metal stud frame wall in Building 4 Revise door escurity glazing and hardware in Building 7 Change exterior wall paint color Relocate electrical boxes	SC 0ther 0 Other 6 E & 0 0 FC 6 E & 0 5 SC 7 SC	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364 274 2,774 1,395 32,447 497 36,268 5,696 2,834
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165 CO #165 CO #166 CO #167 CO #168 CO #169 CO #170 CO #171 CO #172 CO #173 CO #174 CO #175 CO #176	Revisions to peremiter security fences Add condensate drain line Revise light fixtures to high security recessed lights Revised sink designs Relocate soap dispensers per ADA Extend HVAC duct work Revised door lever design Add stainless steel toekick plates in Building 4 Replace padlocks in Building 4 lockers Reshape bioswale to accomidate exterior fence pathway Revised door hardware CSFM field inspection revisions Revised pathway to provide electrical room access Add metal stud frame wall in Building 4 Revise door escurity glazing and hardware in Building 7 Change exterior wall paint color Relocate electrical boxes Replacement electrical panels for medium voltage	SC Other   E & O Other   FC   E & O SC   SC   SC   SC   SC   SC   Other   SC   Other	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364 2,74 2,774 1,395 32,447 497 36,268 5,696 2,834 10,237 7,444 33,652
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165 CO #165 CO #166 CO #167 CO #168 CO #169 CO #170 CO #171 CO #172 CO #173 CO #174 CO #175 CO #176	Revisions to peremiter security fences Add condensate drain line Revise light fixtures to high security recessed lights Revised sink designs Relocate soap dispensers per ADA Extend HVAC duct work Revised door lever design Add stainless steel toekick plates in Building 4 Replace padlocks in Building 4 lockers Reshape bioswale to accomidate exterior fence pathway Revised door hardware CSFM field inspection revisions Revised pathway to provide electrical room access Add metal stud frame wall in Building 4 Revise door escurity glazing and hardware in Building 7 Change exterior wall paint color Relocate electrical boxes Replacement electrical panels for medium voltage cables	SC Other   E & O   FC   E & O   SC   SC   SC   SC   SC   SC   Other   SC   Other   SC   Other	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364 2,74 2,774 1,395 32,447 497 36,268 5,696 2,834 10,237 7,444 33,652 39,907
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165 CO #166 CO #167 CO #167 CO #168 CO #169 CO #170 CO #171 CO #172 CO #173 CO #174 CO #175 CO #176 CO #177 CO #177	Revisions to peremiter security fences Add condensate drain line Revise light fixtures to high security recessed lights Revised sink designs Relocate soap dispensers per ADA Extend HVAC duct work Revised door lever design Add stainless steel toekick plates in Building 4 Replace padlocks in Building 4 lockers Reshape bioswale to accomidate exterior fence pathway Revised door hardware CSFM field inspection revisions Revised pathway to provide electrical room access Add metal stud frame wall in Building 4 Revise door escurity glazing and hardware in Building 7 Change exterior wall paint color Relocate electrical boxes Replacement electrical panels for medium voltage cables Add time clock for exterior lighting	SC Other   E & O   FC   E & O   SC   SC   SC   SC   SC   SC   Cther   Other   Other   SC   Other	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364 2,74 2,774 1,395 32,447 497 36,268 5,696 2,834 10,237 7,444 33,652 39,907 2,975
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165 CO #166 CO #167 CO #167 CO #169 CO #170 CO #170 CO #171 CO #172 CO #173 CO #174 CO #175 CO #177 CO #178 CO #179	Revisions to peremiter security fences Add condensate drain line Revise light fixtures to high security recessed lights Revised sink designs Relocate soap dispensers per ADA Extend HVAC duct work Revised door lever design Add stainless steel toekick plates in Building 4 Replace padlocks in Building 4 lockers Reshape bioswale to accomidate exterior fence pathway Revised door hardware CSFM field inspection revisions Revised pathway to provide electrical room access Add metal stud frame wall in Building 4 Revise door escurity glazing and hardware in Building 7 Change exterior wall paint color Relocate electrical boxes Replacement electrical panels for medium voltage cables Add time clock for exterior lighting Add electrical power to room 159 in Building 4	SC Other   E & O   FC   E & O   SC   SC   SC   SC   SC   FC   SC   Other   SC	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364 274 2,774 1,395 32,447 497 36,268 5,696 2,834 10,237 7,444 33,652 39,907 2,975 1,181
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165 CO #166 CO #167 CO #167 CO #169 CO #170 CO #170 CO #171 CO #172 CO #173 CO #174 CO #175 CO #177 CO #177 CO #178 CO #179 CO #180	Revisions to peremiter security fences Add condensate drain line Revise light fixtures to high security recessed lights Revised sink designs Relocate soap dispensers per ADA Extend HVAC duct work Revised door lever design Add stainless steel toekick plates in Building 4 Replace padlocks in Building 4 lockers Reshape bioswale to accomidate exterior fence pathway Revised door hardware CSFM field inspection revisions Revised pathway to provide electrical room access Add metal stud frame wall in Building 4 Revise door escurity glazing and hardware in Building 7 Change exterior wall paint color Relocate electrical boxes Replacement electrical panels for medium voltage cables Add time clock for exterior lighting Add electrical power to room 159 in Building 4	SC Other   E & O Other   FC E & O   SC SC SC SC SC Other   SC Other   SC Other   SC Other   SC Other   SC SC SC SC SC SC SC SC SC SC	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364 274 2,774 1,395 32,447 497 36,268 5,696 2,834 10,237 7,444 33,652 39,907 2,975 1,181 4,357
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165 CO #166 CO #167 CO #167 CO #167 CO #169 CO #170 CO #170 CO #171 CO #172 CO #173 CO #174 CO #175 CO #177 CO #177 CO #178 CO #179 CO #180 CO #181	Revisions to peremiter security fences Add condensate drain line Revise light fixtures to high security recessed lights Revised sink designs Relocate soap dispensers per ADA Extend HVAC duct work Revised door lever design Add stainless steel toekick plates in Building 4 Replace padlocks in Building 4 lockers Reshape bioswale to accomidate exterior fence pathway Revised door hardware CSFM field inspection revisions Revised pathway to provide electrical room access Add metal stud frame wall in Building 4 Revise door escurity glazing and hardware in Building 7 Change exterior wall paint color Relocate electrical boxes Replacement electrical panels for medium voltage cables Add time clock for exterior lighting Add electrical power to room 159 in Building 4 Add carpet tile in Buildings 1A/1B Credit for deleted duct liner insulation	SC Other   E & O Other   FC E & O   SC SC SC SC Other   SC Other   SC Other   SC Other   SC Other   SC C TBD	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364 274 2,774 1,395 32,447 497 36,268 5,696 2,834 10,237 7,444 33,652 39,907 2,975 1,181 4,357 (4,242)
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165 CO #166 CO #167 CO #167 CO #167 CO #170 CO #170 CO #170 CO #171 CO #172 CO #173 CO #174 CO #175 CO #177 CO #178 CO #179 CO #180 CO #181 CO #182	Revisions to peremiter security fences Add condensate drain line Revise light fixtures to high security recessed lights Revised sink designs Relocate soap dispensers per ADA Extend HVAC duct work Revised door lever design Add stainless steel toekick plates in Building 4 Replace padlocks in Building 4 lockers Reshape bioswale to accomidate exterior fence pathway Revised door hardware CSFM field inspection revisions Revised pathway to provide electrical room access Add metal stud frame wall in Building 4 Revise door escurity glazing and hardware in Building 7 Change exterior wall paint color Relocate electrical boxes Replacement electrical panels for medium voltage cables Add time clock for exterior lighting Add electrical power to room 159 in Building 4 Add carpet tile in Buildings 1A/1B Credit for deleted duct liner insulation Credit for revised work on Building 7	SC Other   E & 0   FC   E & 0   SC   SC   SC   SC   Other   SC   Other   SC   Other   FC   E & 0   SC   Other   FC   E & 0   SC   SC   Other   FC   E & 0   SC	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364 274 2,774 1,395 32,447 497 36,268 5,696 2,834 10,237 7,444 33,652 39,907 2,975 1,181 4,357 (4,242) (803)
	CO #159 CO #160 CO #162 CO #163 CO #164 CO #165 CO #166 CO #167 CO #167 CO #167 CO #169 CO #170 CO #170 CO #171 CO #172 CO #173 CO #174 CO #175 CO #177 CO #177 CO #178 CO #179 CO #180 CO #181	Revisions to peremiter security fences Add condensate drain line Revise light fixtures to high security recessed lights Revised sink designs Relocate soap dispensers per ADA Extend HVAC duct work Revised door lever design Add stainless steel toekick plates in Building 4 Replace padlocks in Building 4 lockers Reshape bioswale to accomidate exterior fence pathway Revised door hardware CSFM field inspection revisions Revised pathway to provide electrical room access Add metal stud frame wall in Building 4 Revise door escurity glazing and hardware in Building 7 Change exterior wall paint color Relocate electrical boxes Replacement electrical panels for medium voltage cables Add time clock for exterior lighting Add electrical power to room 159 in Building 4 Add carpet tile in Buildings 1A/1B Credit for deleted duct liner insulation	SC Other   E & O Other   FC E & O   SC SC SC SC Other   SC Other   SC Other   SC Other   SC Other   SC C TBD	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	4,561 4,575 1,448 10,294 532 1,480 2,364 274 2,774 1,395 32,447 497 36,268 5,696 2,834 10,237 7,444 33,652 39,907 2,975 1,181 4,357 (4,242)

C 0 #136 Add ADA compliant concrete walkway SC \$ 18,636 C 0 #138 Revised intraction system SC \$ 60,552 C 0 #138 Revised exterior sign and lettering TBD \$ 12,303 C 0 #139 Security bars mokup SC \$ 2,555 C 0 #139 Security bars mokup SC \$ 2,555 C 0 #139 Unused change order amount credit TBD \$ 14,3479 Modif officer station due to conflict with fire alarm Modif officer station due to conflict with fire alarm Modif officer station due to conflict with fire alarm Modif officer station due to conflict with fire alarm Modif officer station due to conflict with fire alarm Modif officer station due to conflict with fire alarm Modif officer station due to conflict with fire alarm Modif officer station due to conflict with fire alarm Modif officer station due to conflict with fire alarm Modif officer station due to conflict with fire alarm Modif officer station Add power outlies to officer stations SC \$ 12,849 C 0 #139 Replace door strikes for monitoring system E & 0 \$ 4,949 C 0 #138 Replace door strikes for monitoring system E & 0 \$ 5,783 C 0 #201 Add gi defence barrier TBD \$ 5,783 C 0 #201 Add gi defence barrier TBD \$ 5,783 C 0 #201 Add file defense barrier installation TBD \$ 5,783 C 0 #201 Add file defense barrier installation TBD \$ 5,6424 C 0 #211 Additional labor for dig defense barrier installation TBD \$ 5,6424 C 0 #211 Add file af 5 Added Lighting Control Device C 0 #201 Add file af State Amount for Time Impact Analyss #2 Other \$ 125,873 C 0 #207 Revised color scheme mockups TBD \$ 5,122,873 C 0 #208 C 0 #204 C 76M file alsocutive shorts TBD \$ 12,274 C 0 #228 C 0 #234 C reduit no rigit on pisse difference TBD \$ 1,223 C 0 #234 C reduit no rigit on pisse difference TBD \$ 1,224 C 0 #234 C reduit for imgeton ping size difference TBD \$ 1,224 C 0 #224 Revised action scheme mockups TBD \$ 12,274 C 0 #224 Revised action scheme mockups TBD \$ 12,274 C 0 #224 Revised action scheme mockups TBD \$ 12,274 C 0 #224 Revised action scheme mockups TBD \$ 12,274 C 0 #224 Revised action scheme mockups TBD \$ 12,274 C 0 #224 Revised action sch						
CO #187         Revised irrigation system         SC         \$ 605.52           CO #188         Revised exterior sign and lettering         TBD         \$         5.408           CO #191         Security bars mockup         SC         \$         2.154           CO #192         Unused change order amount credit         TBD         \$         (43,479)           CO #193         parel         TBD         \$         1.831           CO #193         parel         TBD         \$         1.841           CO #193         Patch and repair missing fire protection material         FC         \$         2.741           CO #195         Relocate fire hydrant bollards         TBD         \$         1.843           CO #197         Add power outlets to officer stations         SC         \$         3.849           CO #200         Install revised infraction system         TBD         \$         5.732           CO #211         Add fing defence barrier         TBD         \$         5.732           CO #201         Add fing a fore around staff parking         TBD         \$         5.738           CO #217         Add fine around staff parking         TBD         \$         5.738           CO #217         Add fine around staff parking	2. BOS Approval 2019-11-05					1,370
CO #188         Revised exterior sign and lettering         TBD         S         5,408           CO #189         Concrete wall work related to exterior sign revisions         TBD         S         1,230           CO #191         Security bars mockup         SC         S         2,134           CO #193         Modif Officer station due to conflict with fire alarm         TBD         S         1,631           CO #193         Patch and repair missing fire protection material         FC         S         2,744           CO #194         Patch and repair missing fire protection material         FC         S         2,744           CO #195         revised landscape and irigation systems         SC         S         3,900           CO #191         Add power outlets to officer stations         SC         S         3,900           CO #201         Add id dig defence barrier         TBD         S         5,788           CO #211         Additional labor for dig defense barrier installation         TBD         S         2,710           CO #221         Additional labor for dig defense barrier installation         TBD         S         2,718           RF #852 Building #5 Added Lighting Control Device         TBD         S         2,728           CO #220         Fit #852 Bui						
CO #189 Concrete wall work related to exterior sign revisions TBD \$ 11,230 CO #191 Security hars mockup SC \$ 2,145 CO #192 Unused change order amount credit TBD \$ (43,479 Wodft officer station due to conflict with fire alarm CO #193 parel TBC \$ 1,847 CO #193 Patch and repair missing fire protection material FC \$ 2,744 CO #195 Relocate fire hydrant bollards TBD \$ 1,761 CO #195 Relocate fire hydrant bollards TBD \$ 1,761 CO #197 Add power outlets to officer stations SC \$ 15,722 CO #197 Add power outlets to officer stations SC \$ 18,499 CO #200 Install revised indicates fires for molitoring system CO #201 Add dig defence barrier TBD \$ 2,864 CO #201 Add dig defence barrier TBD \$ 2,864 CO #202 Install revised indication figures TBD \$ 2,500 CO #201 Add dig defence barrier TBD \$ 5,788 CO #202 Install revised indication for tig defense barrier installation TBD \$ 2,500 CO #202 fabric Revised addication for tig defense barrier installation TBD \$ 2,5100 CO #202 fabric Revised addication for tig defense barrier TBD \$ 6,7,718 RFI #862 building # 5 Added Lighting Control Device RFI #862 building # 5 Added Lighting Control Device CO Pending ir orom #107 S 5,788 CO #202 Fabric Revised color scheme mockups TBD \$ 5,538 CO #209 Install light security forcing to no climb CO #209 Revised color scheme mockups TBD \$ 5,538 CO #209 CO #200 CO #806 Partially Settled Amount for Time impact Analysk #2 Other \$ 12,5673 2. Pending BOS Approval - 2020-O O # Pendir Dig defence barrier for Phase II \$ C \$ 2,000 CO #203 Revised bird right security france trans TBD \$ 1,2707 CO #205 Revised back to arrier for Phase II \$ C \$ 2,000 CO #206 Revise backtball hop design TBD \$ 16,001 CO #207 Add irrigation system in courtyrad TBD \$ 100,466 CO #212 Add irrigation system in the fire rating Revised security games TBD \$ 100,466 CO #221 Add irrigation system in courtyrad TBD \$ 100,466 CO #222 Revise detail hop design TBD \$ 100,465 CO #223 Revise detail hop or windwr frame and glating TC \$ 93,897 CO #224 Revise detail hop or windwr frame and glating TBD \$ 5,5,24		CO #187	<b>2</b> ,			•
C0 H191         Security bars mackup         SC         \$<		CO #188	Revised exterior sign and lettering	TBD	\$	5,408
CO #192         Unused change order amount credit.         TBD         S         (43,479           Modif officer station due to conflict with fire alarm         TBD         S         1,831           CO #193         panel         TBD         S         1,831           CO #194         Patch and repair missing fire protection material         FC         S         2,744           CO #195         Relocate fire hydrant bollards         TBD         S         1,831           CO #196         revised landscape and irrigation system         S         S         5,725           CO #197         Add power outlets to officer stations         SC         S         1,894           CO #201         Add dig defence barrier         TBD         S         2,866           CO #201         Add fence around staff parking         TBD         S         5,788           CO #201         Add fence around staff parking         TBD         S         2,870           CO #201         Add fence around staff parking         TBD         S         3,472           CO #204         fabric         room #107         E & O         S         3,472           2. Bod Approval 2019-11-05 Total         S         13,452         S         3,472           2			Concrete wall work related to exterior sign revisions	TBD	\$	11,230
Modift officer station due to conflict with fire alarm       TBD       \$       18.81         CO #194       Patch and repair missing fire protection material       FC       \$       2.741         CO #195       Relocate fire hydrant bollards       TBD       \$       1.761         CO #196       Relocate fire hydrant bollards       TBD       \$       1.761         CO #197       Add power outlets to officer stations       SC       \$       4.949         CO #197       Add power outlets to officer stations       SC       \$       4.949         CO #200       Install revised inrigation plan       TBD       \$       2.8,664         CO #201       Add fig defence barrier       TBD       \$       2.8,664         CO #201       Add fig defence barrier       TBD       \$       2.6,780         CO #201       Add fig defence barrier       TBD       \$       2.6,780         CO #201       Add fig defence barrier       TBD       \$       2.6,780         CO #201       Add fig defence barrier       TBD       \$       2.6,780         CO #201       Rabil #52 Building #5 Added Lighting Control Device       FE       \$       3.4,722         2. Eorded by Change Order Savin       CO #2040       Partially Settled Amount for		CO #191	, ,	SC		2,154
CO #193 CO #194 CO #195 Relocate fire hydrant bolardsFBD\$1.81 2.74 2.74CO #195 CO #195 CO #195 CO #195 CO #195 CO #195 CO #195 CO #195 CO #198 CO #198 CO #198 Replace door strikes for monitoring system CO #200 Add gower outlets to officer stations SCSC\$5.7226 2.741 2.8564 3.000CO #201 CO #202 Co #201 Co #202 Co #201 Co #202 Co #201 Co #202 Co #203 Co #203 Co #204 Co #204 Co #205 Co #205 Co #205 Co #206 Co #206 Co #207 Co #206 Co #207 Revised color scheme mockups Co #208 Co #209 Co #204 Co #204 Co #206 Co #204 Co #204 Co #204 Co #204 Co #204 Co #205 Co #204 Co #2		CO #192	-	TBD	\$	(43,479)
CO #194       Patch and repair missing fire protection material       FC       \$ 1,761         CO #195       Relocate fire hydrach bollards       FBD       \$ 1,761         CO #197       Red power outlets to officer stations       SC       \$ 1,849         CO #197       Red power outlets to officer stations       SC       \$ 1,849         CO #107       Redplace door strikes for monitoring system       E & O       \$ 4,994         CO #200       Install revised irrigation plan       TBD       \$ 226,664         CO #211       Add tional labor for dig defense barrier installation       TBD       \$ 2,788         CO #211       Add tional labor for dig defense barrier installation       TBD       \$ 2,61,001         CO #211       Add tional labor for dig defense barrier installation       TBD       \$ 6,2,718         CO #200       fabric       TBD       \$ 6,2,718       \$ 6,3471         CO #201       fabric       TBD       \$ 6,2,718       \$ 3,472         Z. BOS Approval 2019-11-05 Total       CO #000       Partially Settled Amount for Time Impact Analys #2       Other       \$ 125,873         CO #203       Creatit for irrigation piping size difference       TBD       \$ 12,274         CO #204       Revised barrier for Phase II       \$ 5 2       2,200			Modift officer station due to conflict with fire alarm			
CO #195 Relocate fire hydrant bollards Fib 1761 CO #197 Add power outlets to officer stations SC \$ 57226 CO #197 Add power outlets to officer stations SC \$ 1,849 CO #198 Replace door strikes for monitoring system E & O \$ 4,994 CO #200 Install revised irrigation plan TB0 \$ 226,664 CO #201 Add dig defence barrier TB0 \$ 3,000 CO #211 Add fience around staff parking TB0 \$ 261,001 CO #211 Add fience around staff parking TB0 \$ 261,001 CO #212 fabric RF1 #862 Building #5 Added Lighting Control Device RF1 #862 Building #5 Added Lighting Control Device CO #200 Install lever for dig defence barrier installation TB0 \$ 261,001 CO #200 Fabric RF1 #862 Building #5 Added Lighting Control Device RF1 #862 Building #5 Added Lighting Control Device CO #200 Install light security shrouds in req yard \$ \$ 125,873 CO #200 Install light security shrouds in req yard \$ \$ 125,873 CO #200 Install light security shrouds in req yard \$ \$ 125,873 CO #200 Install light security shrouds in req yard \$ \$ 1,25,873 CO #202 Revised color scheme mockups TB0 \$ 1,25,873 CO #202 Revised around staff parking TB0 \$ 1,25,873 CO #204 CS/H field inspection revisions TB0 \$ 1,20,204 CO #204 CS/H field inspection revisions TB0 \$ 1,20,204 CO #204 CS/H field inspection revisions TB0 \$ 1,22,714 CO #204 Revised backetball hoog design TB0 \$ 1,22,714 Revised security glazing to meet fire rating Revised security glazing to meet fire rati		CO #193	panel	TBD		1,831
CO #196       revised landscape and irrigation systems       SC       \$ 57,283         CO #197       Add power outlets to officer stations       SC       \$ 1,849         CO #190       Replace door strikes for monitoring system       E & O       \$ 4,994         CO #200       Install revised irrigation plan       TBD       \$ 226,664         CO #211       Add dig defence barrier       TBD       \$ 226,664         CO #217       Add fence around staff parking       TBD       \$ 261,001         CO #217       Add fence around staff parking       TBD       \$ 261,001         CO #207       Add fence around staff parking       TBD       \$ 261,001         CO #209       Fabric       TBD       \$ 261,001         CO #200       fabric       TBD       \$ 261,001         CO #201       Fabric       TBD       \$ 261,001         CO #202       Fabric       TBD       \$ 26,718         RFI #862 Building #5 Added Lighting Control Device       F       \$ 2,718         RE #1#862 Building #5 Added Lighting Control Device       \$ 125,873       \$ 695,484         2. Funded by Change Order Savin       CO #000       Partially Settled Amount for Time Impact Analys #2       Other       \$ 125,873         CO #201       Revised actor scheme mock		CO #194	Patch and repair missing fire protection material	FC		2,741
C0 #197       Add power outlets to officer stations       SC       \$ 1,849         C0 #198       Replace door strikes for monitoring system       E & O       \$ 28,664         C0 #200       Install revised irrigation plan       TBD       \$ 28,664         C0 #201       Add fig defence barrier       TBD       \$ 28,664         C0 #217       Add fence around staff parking       TBD       \$ 261,001         C0 #217       Add fence around staff parking       TBD       \$ 261,001         C0 #207       Fabric       TBD       \$ 261,001         C0 #207       Fabric       TBD       \$ 263,002         C0 #207       Fabric       TBD       \$ 693,484         2. BOS Approval 2019-11-05 Total       TBD       \$ 695,484         2. Funded by Change Order Savin       C0 #000       Partially Settled Amount for Time Impact Analyss #2       Other       \$ 132,587         2. Funded by Change Order Savings Total       C0 #207       Revise doors scheme mockups       TBD       \$ 12,873         2. Funded by Change Order Savings Total       C0 #204       CSFM filed inspection revisions       TBD       \$ 12,873         2. Funded by Change Order Savings Total       SC       S 40,000       S 20,000       S 20,000         C0 #204       CSFM filed inspectio			•			1,761
CO #198         Replace door strikes for monitoring system         E & O         S         4.994           CO #200         Install revised irrigation plan         TBD         S         28.664           CO #211         Add tig defence barrier         TBD         S         28.664           CO #217         Add fence around staff parking         TBD         S         26.1001           CO #217         Add fence around staff parking         TBD         S         62.718           CO #217         Add fence around staff parking         TBD         S         62.718           CO #217         Add fence around staff parking         TBD         S         62.718           CO #207         Fabric         TBD         S         635.484           2. Funded by Change Order Savin         CO #000         Partially Settled Amount for Time Impact Analyss #2         Other         S         125.873           CO #207         Revised color scheme mockups         TBD         S         136.550           2. Funded by Change Order Savin         CO #209         Install light security shroush inre vard         S         125.873           2. Funded by Change Order Saving Total         S         126.00         S         125.267           2. Funded by Change Order Saving Total		CO #196				57,226
CO #200 Install revised irrigation plan TBD \$ 28,644 CO #201 Add dig defence barrier TBD \$ 3,000 CO #217 Add fence around staff parking TBD \$ 27,88 CO #2217 Add fence around staff parking TBD \$ 26,718 CO #220 fabric around staff parking TBD \$ 26,718 CO #220 fabric around staff parking TBD \$ 62,718 RFI #862 Building #5 Added Lighting Control Device CO Pendin room #107 E & 0 \$ 3,472 2. BOS Approval 2019-11-05 Total CO #207 Revised color scheme mockups #2 Other \$ 125,873 CO #229 Paint accent wall in Building 4 photography area TBD \$ 125,873 CO #229 Paint accent wall in Building 4 photography area TBD \$ 1,203 2. Funded by Change Order Savin CO #000 Partially Settled Amount for Time Impact Analyss #2 Other \$ 125,873 CO #229 Paint accent wall in Building 4 photography area TBD \$ 1,203 2. Funded by Change Order Saving Total \$ 134,555 2. Pending BOS Approval - 202-0 CO # Pendin Dig defence barrier for Phase II \$ \$ 20,000 CO #229 Paint accent wall in Building 4 photography area TBD \$ 12,203 2. Pending BOS Approval - 202-0 CO # Pendin Dig defence barrier for Phase II \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$		CO #197				1,849
CO #201       Add dig defence barrier       TBD       \$       3,000         CO #211       Add fince around staff parking       TBD       \$       5,788         CO #217       Add fence around staff parking       TBD       \$       25,788         CO #210       Add fence around staff parking       TBD       \$       26,001         CO #220       fabric       TBD       \$       662,718         CO #211       Add fence around staff parking       TBD       \$       62,718         CO #200       Fabric       TBD       \$       62,718         RFI #862 Building # 5 Added Lighting Control Device       TBD       \$       63,472         2. Funded by Change Order Savin       CO #060       Partially Settled Amount for Time Impact Analyss #2       Other       \$       125,873         CO #207       Revised color scheme mockups       TBD       \$       153,523         CO #209       Install light security shrouds in rec yard       SC       \$       14,292         2. Funded by Change Order Saving Total       S       12,233       12,233       12,233       12,233       132,553       132,254       132,254       132,254       132,274       CO #206       Revise dair condition system       TBD       \$       12,274 <td></td> <td></td> <td></td> <td>E &amp; O</td> <td></td> <td></td>				E & O		
CO #211       Additional labor for dig defense barrier installation       TBD       \$       5,788         CO #220       Fabric       TBD       \$       26,001         CO #220       Fabric       TBD       \$       66,010         RH #862 Building # 5 Added Lighting Control Device       TBD       \$       6695,484         2. BOS Approval 2019-11-05 Total       CO #200       Partially Settled Amount for Time Impact Analyss #2       Other       \$       125,873         2. Funded by Change Order Savin       CO #207       Revised color scheme mockups       TBD       \$       125,873         CO #209       Install light security shrouds in rec yard       SC       \$       14,292         CO #209       Install light security shrouds in rec yard       SC       \$       14,292         CO #209       Install light security for Naise II       SC       \$       20,400         2. Funded by Change Order Saving Total       \$       1365,550       \$       20,000       \$       12,274         CO #204       CSFM field inspection revisions       TBD       \$       12,274       \$       13,126         2. Funded by Change Order Saving Cotal       CO #204       CSFM field inspection revisions       TBD       \$       12,274         CO #2						
CO #217 Add fence around staff parking TBD \$ 261,001 Change intermediate security fencing to no climb fabric Fill #862 Building # 5 Added Lighting Control Device FI #862 Building # 5 Added Lighting Control Device CO Pendin <sub>1</sub> room #107 E & 0 \$ 3,472 2. BOS Approval 2019-11-05 Total \$ 695,484 2. Funded by Change Order Savin CO #060 Partially Settled Amount for Time Impact Analyss #2 Other \$ 125,873 CO #209 Install light security shrouds in rec yard SC \$ 14,292 CO #209 Install light security shrouds in rec yard SC \$ 14,292 2. Pending BOS Approval - 2020-0 CO # Pendin CO #209 Paint accent wall in Building 4 photography area TBD \$ 1,203 2. Pending BOS Approval - 2020-0 CO # Pendir CO #208 Revise Baketball hoop design TBD \$ 12,274 CO #206 Revise Baketball hoop design TBD \$ 13,126 CO #212 Revised air condition system in courtyard TBD \$ 13,126 CO #212 Revised air condition system TBD \$ 20,0107 CO #214 Added privacy screens in sleeping rooms TBD \$ 3,004 CO #215 requirements TBD \$ 3,004 CO #216 Add fires moke dampers E & 0 \$ 24,415 CO #218 Replace peremiter fence privacy fabric TBD \$ 3,004 CO #224 Add security glazing to meet fire rating Revised decurity glazing to meet fire rating CO #214 Add descurity cameras TBD \$ 3,004 CO #224 Add security cameras TBD \$ 3,004 CO #224 Add security cameras TBD \$ 3,004 CO #224 Revise detention door window frame and glazing TBD \$ 22,549 Add drivered fire smoke dampers E & 0 \$ 24,415 CO #224 Revise detention door window frame and glazing FC \$ 98,495 CO #224 Revise detention door window frame and glazing TBD \$ 5,246 CO #225 Revise detention door window frame and glazing TBD \$ 5,246 CO #226 Added flush control		CO #201	Add dig defence barrier	TBD	\$	3,000
CO #217 Add fence around staff parking TBD \$ 261,001 Change intermediate security fencing to no climb fabric Fill #862 Building # 5 Added Lighting Control Device FI #862 Building # 5 Added Lighting Control Device CO Pendin <sub>1</sub> room #107 E & 0 \$ 3,472 2. BOS Approval 2019-11-05 Total \$ 695,484 2. Funded by Change Order Savin CO #060 Partially Settled Amount for Time Impact Analyss #2 Other \$ 125,873 CO #209 Install light security shrouds in rec yard SC \$ 14,292 CO #209 Install light security shrouds in rec yard SC \$ 14,292 2. Pending BOS Approval - 2020-0 CO # Pendin CO #209 Paint accent wall in Building 4 photography area TBD \$ 1,203 2. Pending BOS Approval - 2020-0 CO # Pendir CO #208 Revise Baketball hoop design TBD \$ 12,274 CO #206 Revise Baketball hoop design TBD \$ 13,126 CO #212 Revised air condition system in courtyard TBD \$ 13,126 CO #212 Revised air condition system TBD \$ 20,0107 CO #214 Added privacy screens in sleeping rooms TBD \$ 3,004 CO #215 requirements TBD \$ 3,004 CO #216 Add fires moke dampers E & 0 \$ 24,415 CO #218 Replace peremiter fence privacy fabric TBD \$ 3,004 CO #224 Add security glazing to meet fire rating Revised decurity glazing to meet fire rating CO #214 Add descurity cameras TBD \$ 3,004 CO #224 Add security cameras TBD \$ 3,004 CO #224 Add security cameras TBD \$ 3,004 CO #224 Revise detention door window frame and glazing TBD \$ 22,549 Add drivered fire smoke dampers E & 0 \$ 24,415 CO #224 Revise detention door window frame and glazing FC \$ 98,495 CO #224 Revise detention door window frame and glazing TBD \$ 5,246 CO #225 Revise detention door window frame and glazing TBD \$ 5,246 CO #226 Added flush control		CO #211	Additional labor for dig defense barrier installation	TBD	\$	5,788
CO #220 fabric RF #362 Building # 5 Added Lighting Control Device RF #362 Building # 5 Added Lighting Control Device CO Pendin room #107 E&O \$ 3,472 2. BOS Approval 2019-11-05 Total \$ 695,484 2. Funded by Change Order Savin CO #060 Partially Settled Amount for Time Impact Analyss #2 Other \$ 125,873 CO #209 Install light security shrouds in rec yard SC \$ 14,292 CO #213 Credit for irrigation piping size difference TBD \$ 5,540 CO #209 Paint accent wall in Building 4 photography area TBD \$ 12,030 2. Pending BOS Approval - 2020-0 CO # Pendin Dig defence barrier for Phase II SC \$ 20,000 CO #209 CO #206 Revise basketball hoop design TBD \$ 16,700 CO #208 Revised air condition system TBD \$ 13,126 CO #212 Revised dead of wall construction TBD \$ 13,026 CO #212 Revised air condition system TBD \$ 13,046 CO #214 Adde privacy screens in sleeping rooms TBD \$ 3,004 CO #215 Revised aecurity glazing to meet fire rating Revised security glazing to meet fire rating CO #216 Add intergende taeseurity face between gym and Add intermediate security face between gym and Add intermediate security glazing TBD \$ 24,415 CO #218 Revise dereminer for Phase TBD \$ 24,415 CO #218 Revised aerconstruction TBD \$ 3,004 CO #218 Revised aerconstruction TBD \$ 24,415 CO #218 Revised peremiter fence privacy fabric TBD \$ 24,415 CO #218 Revised peremiter fence privacy fabric TBD \$ 24,415 CO #218 Revised derivacy screens in sleeping rooms TBD \$ 24,415 CO #218 Revised derivacy screens in sleeping rooms TBD \$ 24,415 CO #218 Revised derivacy screens in sleeping TBD \$ 14,930 CO #224 Add intermediate security fabric TBD \$ 24,415 CO #224 Revise detention door window frame and glazing TBD \$ 98,472 CO #224 Revise detention door window frame and glazing TBD \$ 3,84,93 CO #224 Revise detention door window frame and glazing TBD \$ 3,84,08 CO #225 Revise detention door window frame and glazing TBD \$ 5,52,46 CO #226 Added fluks control valves for toilet units in Building 2 TBD \$ 6,877 Add privacy film in doors, change security locks CO #228 throughout project TBD \$ 11,933		CO #217	Add fence around staff parking	TBD		261,001
FIF #862 Building # 5 Added Lighting Control Device           CO Pendin         room #107         E & O         \$         695,484           2. BOS Approval 2019-11-05 Total         \$         695,484           2. Funded by Change Order Savin         CO #060         Partially Settled Amount for Time Impact Analyss #2         Other         \$         125,873           CO #209         Install light security shrouds in rec yard         SC         \$         14292           CO #213         Credit for irrigation piping size difference         TBD         \$         136,550           2. Funded by Change Order Savings Total         \$         136,550           2. Funded by Change Order Savings Total         \$         136,550           2. Pending BOS Approval - 2020-0         C0 # Pendir         Dig defence barrier for Phase II         SC         2           2. Pending BOS Approval - 2020-0         C0 # Pendir         Dig defence barrier for Phase II         SC         2         2 <t< td=""><td></td><td></td><td>Change intermediate security fencing to no climb</td><td></td><td></td><td></td></t<>			Change intermediate security fencing to no climb			
CO Pendinroom #107E & O\$3,4722. BOS Approval 2019-11-05 Total\$695,4842. Funded by Change Order SavinCO #000Partially Settled Amount for Time Impact Analyss #2Other\$125,873CO #207Revised color scheme mockupsTBD\$5533CO #209Install light security shrouds in rec yardSC\$14,292CO #213Credit for irrigation piping size differenceTBD\$1,2032. Funded by Change Order Savings TotalS136,550\$136,5502. Pending BOS Approval - 2020-0CO # PendinDig defence barrier for Phase IISC\$20,000CO #204CSFM field inspection revisionsTBD\$12,274CO #205Revisea barcondition systemTBD\$20,010CO #206Revise barcondition systemTBD\$13,126CO #210Add irrigation system in courtyardTBD\$130,460CO #212Revised air condition systemTBD\$3,004CO #215requirementsTBD\$3,004CO #216Add firre groke dampersE & O\$24,415CO #217Add security camerasTBD\$2,5,549CO #218Replace peremiter fence privacy fabricTBD\$2,5,491CO #224CA exise detention door window frame and glazingFBD\$3,9,472CO #218Revise detention door window frame and glazingFBD\$3,9,472 <td< td=""><td></td><td>CO #220</td><td>fabric</td><td>TBD</td><td>\$</td><td>62,718</td></td<>		CO #220	fabric	TBD	\$	62,718
2. BOS Approval 2019-11-05 Total          2. Funded by Change Order Savin       CO #060       Partially Settled Amount for Time Impact Analyss #2       Other       F         CO #207       Revised color scheme mockups       TBD       \$       125,873         CO #209       Install light security shrouds in rec yard       SC       \$       142,922         CO #209       Install light security shrouds in rec yard       SC       \$       142,922         CO #209       Paint accent wall in Building 4 photography area       TBD       \$       12,033         2. Funded by Change Order Savings Totat       C       \$       20,000       \$       12,033         2. Fending BOS Approval - 2020-0       CO #204       CSFM field inspection revisions       TBD       \$       02,070         2. Pending BOS Approval - 2020-0       CO #204       CSFM field inspection revisions       TBD       \$       12,033         2. Pending BOS Approval - 2020-0       CO #204       CSFM field inspection revisions       TBD       \$       12,027         CO #204       CSFM field inspection revisions       TBD       \$       12,027         CO #204       CSFM field inspection revisions       TBD       \$       12,027         CO #204       CSFM field inspection revisions       TBD       \$       20,0107 </td <td></td> <td></td> <td>RFI #862 Building # 5 Added Lighting Control Device</td> <td></td> <td></td> <td></td>			RFI #862 Building # 5 Added Lighting Control Device			
2. Funded by Change Order Savin       CO #000       Partially Settled Amount for Time Impact Analyss #2       Other       \$             125,873       CO #207       Revised color scheme mockups       TBD       \$             583       CO #209       Install light security shrouds in rec yard       SC       \$             14,292       CO #213       Credit for irrigation piping size difference       TBD       \$             (5,401       CO #229       Paint accent wall in Building 4 photography area       TBD       \$             (5,401       SC       \$             120,302       CO #229       Paint accent wall in Building 4 photography area       TBD       \$             (5,401       SC       \$             2,0000       CO #204       CO #204       CO #106       File dinspection revisions       TBD       \$             12,274       SC       \$             20,000       CO #204       CO #204       CSFM field inspection revisions       TBD       \$             12,274       CO #208       Revised air condition system       TBD       \$             12,274       CO #208       Revised air condition system       TBD       \$             12,274       CO #204       CSFM field inspection revisions       TBD       \$             12,274       CO #204       CO #204       CSFM field inspection revisions       TBD       \$             12,274       CO #204       CO #204       CA #204       TBD       \$             12,274       CO #214       Add		CO Pendin	room #107	E & O	\$	3,472
CO #207Revised color scheme mockupsTBD\$583CO #209Install light security shrouds in rec yardSC\$14,292CO #213Credit for irrigation piping size differenceTBD\$1,203CO #220Paint accent wall in Building 4 photography areaTBD\$1,2032. Funded by Change Order Savings TotalSC\$20,000CO #204CSFM field inspection revisionsTBD\$12,274CO #206Revise basketball hoop designTBD\$16,700CO #206Revise basketball hoop designTBD\$20,107CO #206Revise basketball noor ystemTBD\$20,107CO #207CO #204Add irrigation system in courtyardTBD\$13,126CO #214Added privacy screens in sleeping roomsTBD\$3,004CO #216Add fire smoke dampersFBD\$3,004CO #216Add fire smoke dampersE & O\$24,415CO #221Add security glazing to meet fire ratingTBD\$25,549CO #221Add security camerasTBD\$14,939Add intermediate security fence between gym andTBD\$25,549CO #224Revise detention door window frame and glazingFD\$98,496CO #225Revise detention door window frame and glazingFD\$55,246CO #226Add echtub control valves for toilet units in Building 2TBD\$5,2,469CO #226 <td< th=""><th>2. BOS Approval 2019-11-05 Total</th><th></th><th></th><th></th><th>\$</th><th>695,484</th></td<>	2. BOS Approval 2019-11-05 Total				\$	695,484
CO #207Revised color scheme mockupsTBD\$583CO #209Install light security shrouds in rec yardSC\$14,292CO #213Credit for irrigation piping size differenceTBD\$1,203CO #220Paint accent wall in Building 4 photography areaTBD\$1,2032. Funded by Change Order Savings TotalSC\$20,000CO #204CSFM field inspection revisionsTBD\$12,274CO #206Revise basketball hoop designTBD\$16,700CO #206Revise basketball hoop designTBD\$20,107CO #206Revise basketball noor ystemTBD\$20,107CO #207CO #204Add irrigation system in courtyardTBD\$13,126CO #214Added privacy screens in sleeping roomsTBD\$3,004CO #216Add fire smoke dampersFBD\$3,004CO #216Add fire smoke dampersE & O\$24,415CO #221Add security glazing to meet fire ratingTBD\$25,549CO #221Add security camerasTBD\$14,939Add intermediate security fence between gym andTBD\$25,549CO #224Revise detention door window frame and glazingFD\$98,496CO #225Revise detention door window frame and glazingFD\$55,246CO #226Add echtub control valves for toilet units in Building 2TBD\$5,2,469CO #226 <td< td=""><td>2. Funded by Change Order Savin</td><td>CO #060</td><td>Partially Settled Amount for Time Impact Analyss #2</td><td>Other</td><td>Ś</td><td>125.873</td></td<>	2. Funded by Change Order Savin	CO #060	Partially Settled Amount for Time Impact Analyss #2	Other	Ś	125.873
CO #209Install light security shrouds in rec yardSC\$14,292CO #213Credit for irrigation piping size differenceTBD\$(5,401)CO #229Paint accent wall in Building 4 photography areaTBD\$1,2032. Funded by Change Order Savings TotalSC\$20,000SC\$20,000CO #204CSFM field inspection revisionsTBD\$12,274CO #206Revise basketball hoop designTBD\$12,274CO #206Revise dair condition systemTBD\$20,107CO #210Add irrigation system in courtyardTBD\$13,126CO #212Revised head of wall constructionTBD\$100,466CO #212Revised security glazing to meet fire ratingRevised security glazing to meet fire ratingRevised security glazing to meet fire ratingCO #218Replace peremiter fence privacy fabricTBD\$22,401Add intermediate security fence between gym andCO #224Add security camerasTBD\$CO #223Revise drain design in peremiter fence walkwayTBD\$98,472CO #224Revise drain design in peremiter fence walkwayTBD\$98,496CO #225Revise drain design in peremiter fence walkwayTBD\$98,496CO #226Adde deting no peremiter fence walkwayTBD\$55,246CO #226Added flush control valves for toilet units in Building 2TBD\$\$CO #226Added flush control						583
C0 #213 C0 #229Credit for irrigation piping size differenceTBD\$(5,401C0 #229Paint accent wall in Building 4 photography areaTBD\$1,2032. Funded by Change Order Savings Total\$136,5502. Pending BOS Approval - 2020-0CO # PendinDig defence barrier for Phase IISC\$20,000C0 #204CSFM field inspection revisionsTBD\$12,274C0 #206Revise basketball hoop designTBD\$16,700C0 #208Revised air condition systemTBD\$100,466C0 #210Add irrigation system in courtyardTBD\$100,466C0 #211Revised head of wall constructionTBD\$100,466C0 #214Added privacy screens in sleeping roomsTBD\$96,023Revised security glazing to meet fire ratingrequirementsTBD\$22,401Add intermediate security fence between gym andCO #214Add dec privacy fabricTBD\$22,401Add intermediate security fence between gym andCO #221Add security camerasTBD\$25,549C0 #212Add security camerasTBD\$25,54994,842C0 #224Revise detention door window frame and glazingFD\$94,842C0 #225Revise detention door window frame and glazingFD\$98,8420C0 #226Added conduit for wireless access pointsTBD\$88,208C0 #226Added conduit for wireless access points<			•			
CO #229Paint accent wall in Building 4 photography areaTBD\$1,2032. Funding BOS Approval - 2020-0CO # Pendir CO #204Dig defence barrier for Phase IISC\$20,000CO #204CSFM field inspection revisionsTBD\$12,274CO #206Revise basketball hoop designTBD\$16,700CO #208Revised air condition systemTBD\$100,466CO #204CSFM field inspection revisionsTBD\$13,126CO #208Revised head of wall constructionTBD\$130,466CO #212Revised head of wall constructionTBD\$100,466CO #214Added privacy screens in sleeping roomsTBD\$96,023Revised security glazing to meet fire ratingTBD\$3,004CO #216Add fire smoke dampersE & O\$24,415CO #218Replace peremiter fence privacy fabricTBD\$25,549CO #221Add security camerasTBD\$25,549CO #223Revise datin design in peremiter fence walkwayTBD\$94,845CO #224Revise detention door window frame and glazingFC\$98,496CO #225Added conduit for wireless access pointsTBD\$5,5,246CO #226Added conduit for wireless access pointsTBD\$6,877Add privacy film in doors, change security locksTBD\$1,933CO #226Added conduit for wireless access pointsTBD\$<						
2. Funded by Change Order Savings Total						
2. Pending BOS Approval - 2020-0         C0 # Pendir         Dig defence barrier for Phase II         SC         \$         20,000           C0 #204         CSFM field inspection revisions         TBD         \$         12,274           C0 #206         Revise basketball hoop design         TBD         \$         16,700           C0 #206         Revised air condition system         TBD         \$         16,700           C0 #210         Add irrigation system in courtyard         TBD         \$         13,126           C0 #214         Added privacy screens in sleeping rooms         TBD         \$         96,023           Revised security glazing to meet fire rating         "         "         *         *         3,004           C0 #215         requirements         TBD         \$         96,023         *         24,415           C0 #216         Add fire smoke dampers         E & O         \$         24,415         *         24,415           C0 #218         Replace peremiter fence privacy fabric         TBD         \$         98,472         *         98,472           C0 #219         Buildings 1A/1B         TBD         \$         25,549         *         94,88         *         94,88         948         *         94,88	2. Funded by Change Order Savings T					136,550
CO #204CSFM field inspection revisionsTBD\$12,274CO #206Revise basketball hoop designTBD\$16,700CO #208Revised air condition systemTBD\$20,107CO #210Add irrigation system in courtyardTBD\$13,126CO #212Revised head of wall constructionTBD\$100,466CO #214Added privacy screens in sleeping roomsTBD\$96,023Revised security glazing to meet fire ratingTBD\$3,004CO #216Add fire smoke dampersE & O\$2,401Add intermediate security fence between gym andTBD\$98,472CO #219Buildings 1A/1BTBD\$98,472CO #221Add security camerasTBD\$14,930CO #223Revise datin design in premiter fence walkwayTBD\$94,896CO #224Revise detention door window frame and glazingFC\$98,496CO #225Added conduit for wireless access pointsTBD\$\$88,208CO #226Added conduit for wireless access pointsTBD\$88,208CO #227Added conduit for wireless access pointsTBD\$88,208CO #228throughout projectTBD\$11,9332. Pending BOS Approval - 2020-03-10 Total\$729,173729,173			Dig defence barrier for Phase II	SC		20,000
CO #206Revise basketball hoop designTBD\$16,700CO #208Revised air condition systemTBD\$20,107CO #210Add irrigation system in courtyardTBD\$13,126CO #212Revised head of wall constructionTBD\$100,466CO #214Added privacy screens in sleeping roomsTBD\$96,023Revised security glazing to meet fire ratingTBD\$3,004CO #215requirementsTBD\$3,004CO #216Add fire smoke dampersE & O\$24,415CO #218Replace peremiter fence privacy fabric Add intermediate security fence between gym andTBD\$98,472CO #221Add security camerasTBD\$98,47225,54914,930CO #223Revise drain design in peremiter fence walkwayTBD\$948CO #224Revise detention door window frame and glazingFC\$98,496CO #225Revise detention door window frame and glazingTBD\$55,246CO #226Added flush control valves for toilet units in Building 2TBD\$6,877Add privacy film in doors, change security locksTBD\$6,877Add privacy film in doors, change security locksTBD\$11,9332. Pending BOS Approval - 2020-03-10 Total\$729,173729,173		CO #204	CSFM field inspection revisions	TBD	\$	12,274
CO #208Revised air condition systemTBD\$20,107CO #210Add irrigation system in courtyardTBD\$13,126CO #212Revised head of wall constructionTBD\$100,466CO #214Added privacy screens in sleeping roomsTBD\$96,023Revised security glazing to meet fire ratingTBD\$3,004CO #215requirementsTBD\$3,004CO #216Add fire smoke dampersE & O\$24,415CO #218Replace peremiter fence privacy fabricTBD\$22,401Add intermediate security fence between gym andTBD\$25,549CO #221Add security camerasTBD\$98,472CO #222Add security camerasTBD\$14,930CO #223Revise detention door window frame and glazingFC\$98,496CO #224Revise detention door window frame and glazingFD\$55,246CO #225Added conduit for wireless access pointsTBD\$6,877Add privacy film in doors, change security locksTBD\$6,877CO #228throughout projectTBD\$55,246CO #228Throughout projectTBD\$11,9332. Pending BOS Approval - 2020-03-10 Total\$729,173729,173		CO #206	Revise basketball hoop design	TBD		16,700
CO #210Add irrigation system in courtyardTBD\$13,126CO #212Revised head of wall constructionTBD\$100,466CO #214Added privacy screens in sleeping roomsTBD\$96,023Revised security glazing to meet fire ratingTBD\$3,004CO #215requirementsTBD\$3,004CO #216Add fire smoke dampersE & O\$24,415CO #218Replace peremiter fence privacy fabricTBD\$22,401Add intermediate security fence between gym andTBD\$98,472CO #219Buildings 1A/1BTBD\$98,472CO #221Add security camerasTBD\$25,549CO #222Add security monitor/TV data cablingTBD\$948CO #223Revise drain design in peremiter fence walkwayTBD\$948CO #224Revise detention door window frame and glazingTBD\$55,246CO #225Revise detention door window frame and glazingTBD\$55,246CO #226Added flush control valves for toilet units in Building 2TBD\$6,877Add privacy film in doors, change security locksTBD\$6,877CO #228throughout projectTBD\$11,9332. Pending BOS Approval - 2020-03-10 Total\$729,173729,173		CO #208	Revised air condition system	TBD		20,107
CO #214Added privacy screens in sleeping rooms Revised security glazing to meet fire ratingTBD\$96,023 96,023 96,024CO #215requirementsTBD\$3,004CO #216Add fire smoke dampersE & O\$24,415CO #218Replace peremiter fence privacy fabric Add intermediate security fence between gym andTBD\$22,401CO #219Buildings 1A/1BTBD\$98,472CO #221Add security camerasTBD\$25,549CO #222Add security monitor/TV data cablingTBD\$14,930CO #223Revise drain design in peremiter fence walkwayTBD\$948CO #224Revise detention door window frame and glazingFC\$98,496CO #225Revise detention door window frame and glazingTBD\$55,246CO #226Added flush control valves for toilet units in Building 2TBD\$58,208CO #226Added conduit for wireless access pointsTBD\$6,877Add privacy film in doors, change security locksCO #228throughout projectTBD\$11,9332. Pending BOS Approval - 2020-03-10 Total5729,173729,173729,173		CO #210	Add irrigation system in courtyard	TBD	\$	13,126
Revised security glazing to meet fire ratingCO #215requirementsTBD\$3,004CO #216Add fire smoke dampersE & O\$24,415CO #218Replace peremiter fence privacy fabricTBD\$22,401Add intermediate security fence between gym andTBD\$98,472CO #219Buildings 1A/1BTBD\$98,472CO #221Add security camerasTBD\$25,549CO #222Add security camerasTBD\$14,930CO #223Revise drain design in peremiter fence walkwayTBD\$98,496CO #224Revise detention door window frame and glazingFC\$98,496CO #225Revise detention door window frame and glazingTBD\$55,246CO #226Added flush control valves for toilet units in Building 2TBD\$88,208CO #226Added conduit for wireless access pointsTBD\$6,877Add privacy film in doors, change security locksTBD\$11,9332. Pending BOS Approval - 2020-03-10 Total <b>5</b> 729,173 <b>729,173</b>		CO #212	Revised head of wall construction	TBD	\$	100,466
CO #215requirementsTBD\$3,004CO #216Add fire smoke dampersE & O\$24,415CO #218Replace peremiter fence privacy fabricTBD\$22,401Add intermediate security fence between gym andAdd intermediate security fence between gym andTBD\$98,472CO #219Buildings 1A/1BTBD\$98,47225,549CO #221Add security camerasTBD\$14,930CO #222Add security monitor/TV data cablingTBD\$948CO #223Revise drain design in peremiter fence walkwayTBD\$948CO #224Revise detention door window frame and glazingFC\$98,496CO #225Revise detention door window frame and glazingTBD\$55,246CO #226Added flush control valves for toilet units in Building 2TBD\$88,208CO #226Added conduit for wireless access pointsTBD\$6,877Add privacy film in doors, change security locksC#228throughout projectTBD\$11,9332. Pending BOS Approval - 2020-03-10 Total\$729,173\$729,173\$729,173		CO #214		TBD	\$	96,023
CO #216Add fire smoke dampersE & O\$24,415CO #218Replace peremiter fence privacy fabricTBD\$22,401Add intermediate security fence between gym andAdd intermediate security fence between gym andTBD\$98,472CO #219Buildings 1A/1BTBD\$98,47225,549CO #221Add security camerasTBD\$14,930CO #222Add security monitor/TV data cablingTBD\$948CO #223Revise drain design in peremiter fence walkwayTBD\$948CO #224Revise detention door window frame and glazingFC\$98,496CO #225Revise detention door window frame and glazingTBD\$55,246CO #226Added flush control valves for toilet units in Building 2TBD\$\$CO #226Added flush control valves for toilet units in Building 2TBD\$6,877Add privacy film in doors, change security locksTBD\$11,9332. Pending BOS Approval - 2020-03-10 Total\$729,173729,173		CO #215		TBD	\$	3,004
CO #218Replace peremiter fence privacy fabricTBD\$22,401Add intermediate security fence between gym andCO #219Buildings 1A/1BTBD\$98,472CO #221Add security camerasTBD\$25,549CO #222Add security monitor/TV data cablingTBD\$14,930CO #223Revise drain design in peremiter fence walkwayTBD\$98,496CO #224Revise detention door window frame and glazingFC\$98,496CO #225Revise detention door window frame and glazingTBD\$55,246CO #226Added flush control valves for toilet units in Building 2TBD\$88,208CO #226Added flush control valves for toilet units in Building 2TBD\$6,877Add privacy film in doors, change security locksTBD\$11,9332. Pending BOS Approval - 2020-03-10 Total\$729,173			•			24,415
CO #221Add security camerasTBD\$25,549CO #222Add security monitor/TV data cablingTBD\$14,930CO #223Revise drain design in peremiter fence walkwayTBD\$948CO #224Revise detention door window frame and glazingFC\$98,496CO #225Revise detention door window frame and glazingTBD\$55,246CO #226Added flush control valves for toilet units in Building 2TBD\$88,208CO #227Added conduit for wireless access pointsTBD\$6,877Add privacy film in doors, change security locksTBD\$11,9332. Pending BOS Approval - 2020-03-10 Total\$729,173729,173						22,401
CO #221Add security camerasTBD\$25,549CO #222Add security monitor/TV data cablingTBD\$14,930CO #223Revise drain design in peremiter fence walkwayTBD\$948CO #224Revise detention door window frame and glazingFC\$98,496CO #225Revise detention door window frame and glazingTBD\$55,246CO #226Added flush control valves for toilet units in Building 2TBD\$88,208CO #227Added conduit for wireless access pointsTBD\$6,877Add privacy film in doors, change security locksTBD\$11,9332. Pending BOS Approval - 2020-03-10 Total\$729,173729,173		CO #219	Buildings 1A/1B	TBD	\$	98,472
CO #222Add security monitor/TV data cablingTBD\$14,930CO #223Revise drain design in peremiter fence walkwayTBD\$948CO #224Revise detention door window frame and glazingFC\$98,496CO #225Revise detention door window frame and glazingTBD\$\$55,246CO #226Added flush control valves for toilet units in Building 2TBD\$\$88,208CO #226Added conduit for wireless access pointsTBD\$6,877Add privacy film in doors, change security locksTBD\$11,9332. Pending BOS Approval - 2020-03-10 Total\$729,173729,173		CO #221	Add security cameras	TBD		25,549
CO #223Revise drain design in peremiter fence walkwayTBD\$948CO #224Revise detention door window frame and glazingFC\$98,496CO #225Revise detention door window frame and glazingTBD\$\$55,246CO #226Added flush control valves for toilet units in Building 2TBD\$88,208CO #227Added conduit for wireless access pointsTBD\$6,877Add privacy film in doors, change security locksTBD\$11,9332. Pending BOS Approval - 2020-03-10 Total\$729,173729,173		CO #222	Add security monitor/TV data cabling	TBD	\$	14,930
CO #225       Revise detention door window frame and glazing       TBD       \$       55,246         CO #226       Added flush control valves for toilet units in Building 2       TBD       \$       88,208         CO #227       Added conduit for wireless access points       TBD       \$       6,877         Add privacy film in doors, change security locks       TBD       \$       11,933         2. Pending BOS Approval - 2020-03-10 Total       \$       729,173		CO #223	Revise drain design in peremiter fence walkway	TBD		948
CO #226       Added flush control valves for toilet units in Building 2       TBD       \$       88,208         CO #227       Added conduit for wireless access points       TBD       \$       6,877         Add privacy film in doors, change security locks       CO #228       throughout project       TBD       \$       11,933         2. Pending BOS Approval - 2020-03-10 Total       \$       729,173		CO #224		FC		98,496
CO #227       Added conduit for wireless access points       TBD       \$       6,877         Add privacy film in doors, change security locks       CO #228       throughout project       TBD       \$       11,933         2. Pending BOS Approval - 2020-03-10 Total       \$       729,173		CO #225	Revise detention door window frame and glazing	TBD	\$	55,246
CO #227       Added conduit for wireless access points       TBD       \$       6,877         Add privacy film in doors, change security locks       CO #228       throughout project       TBD       \$       11,933         2. Pending BOS Approval - 2020-03-10 Total       \$       729,173		CO #226	Added flush control valves for toilet units in Building 2	TBD	\$	88,208
Add privacy film in doors, change security locks           CO #228         throughout project         TBD         \$         11,933           2. Pending BOS Approval - 2020-03-10 Total         \$         729,173			-			6,877
CO #228         throughout project         TBD         \$ 11,933           2. Pending BOS Approval - 2020-03-10 Total         \$ 729,173						,
2. Pending BOS Approval - 2020-03-10 Total \$ 729,173		CO #228		TBD	\$	11,933
	2. Pending BOS Approval - 2020-03-1	0 Total				729,173
	Grand Total				\$	6,494,226

This page intentionally left blank.