## Attachment B



SC='s Scope Change, FC='s Field Change, Other='s Miscellaneous Change, and E & O='s Error and/or Omission

w Labels	Short Description	Official CO	Cn	ange Ord Amount
L. Original Co	ontingency Budget	Туре	\$	4,254,7
CO #001	Storm Drain Modification	E & O	\$	26,5
CO #002	Relocate gas line	E & O	\$	2,1
CO #003	Hazardous Material Removal	FC	\$	6,7
CO #004	Move existing County containers from project site	Other	\$	1,4
CO #005	Credit for reduced bike rack requirement	Other	\$	(2,4
CO #006	Add baby changing stations	Other	\$	3,3
CO #007	Add gas line shutoff	FC	\$	5,8
CO #008	Concrete Masonry Unit wall modifications for plumbing	E & O	\$	1,7
CO #009	Additional work due to unknown ground conditions	FC	\$	112,5
CO #010	Remove and reroute existing concrete encase electrical conduits	FC	\$	21,
CO #011	Relocate existing fiber optic lines	FC	\$	12,
CO #012	Demo existing concrete culverts	FC	\$	4,0
CO #013	Building beam modifications	E & O	\$	23,
O #014	Plumbing repair at Construction Manager Office	FC	\$	
O #015	Added rebar to 4" walls	FC	\$	1,:
O #016	Site portable toilets, wash stations, water - water shutdown	FC	\$	3,
O #017	Replace existing fire hydrant	E & O	\$	3,
CO #018	Unknown plumbing work under concrate slab	E & O	\$	590,
O #019	Additional work due to unknown ground conditions	FC	\$	935,
O #020	Added power to lighting control panel	E & O	\$	1,
O #021	Add steel column at Building 4	E & O	\$	8,
O #022	Revise electrical conduit	Other	\$	(22,
O #023	Storm drain at Building 7	E & O	\$	7,
O #024	Added circuit breater to Building 2	E & O	\$	2,
O #025	Drilling for low voltage	FC	\$	5,
O #026	Lower windows at Building 1B	E & O	\$	15,
O #027	Lower windows at Building 1B	E & O	\$	6,
O #028	Added steel column to Building 6	E & O	\$	8,
O #029	Added power line	E & O	\$	6,
O #030	Lower fire water line	SC	\$	17,
O #031	Reset 6" sewer line	FC	\$	3,
O #032	Exterior wall access door modification	E & O	\$	7,
O #033	Additional welding in Building 7	FC	\$	
O #034	Added fasteners for masonry work	E & O	\$	1,
O #035	Extend Building 4 beams	E & O	\$	2,
O #036	Lower existing water line	FC	\$	40,
O #037	Increase Building 1A exhause fan	E & O	\$	2,
O #038	Replace existing sewer lines	SC	\$	33,
O #039	Added circuit breater to Building 4	E & O	\$	2,
O #040	Added circuit breaker to Building 1A	E & O	\$	1,
O #041	Added circuit breater to Building 5	E & O	\$	1,
O #042	Added circuit breater to Building 6	E & O	\$	1,
O #043	Added circuit breater to Building 6	E & O	\$	1,
O #044	Added conduit supports in Building 7	FC	\$	26,
O #045	Added circuit breater to Building 4	E & O	\$	3,
O #046	Added power/data to Building 7	E & O	\$	3,
O #047	Revise power pathway	E & O	\$	125,
O #048	Revise shower partitions	SC	\$	50,
O #049	Low voltage tie-in	E & O	\$	21,
O #050	Added beams in Building 2	E & O	\$	2,
O #051	Added detention window frames	E & O	\$	z, 5,
O #052	Added manhole	SC	\$	61,
O #052	ADA modifications in Buildings 1A/1B and 2	E & O	\$	20,
O #054	Lintel ledger coordination work	E & O	\$	1,
CO #055	Added footing and column on Building 4	E & O	\$	9,
CO #056	Additional cameras in Building 7	SC	\$	12,
CO #057	Missing circuits for Building 4 HVAC	E & O	\$	11,:

CO #058	Added drop ceilings in Building 1B	E & O	\$	3,621
CO #059	Revised exterior light near lobby	E & O	\$	1,644
CO #061	Sewer system excavation	FC	\$	5,349
CO #062	Revised privacy partitions in Building 4	E & O	\$	9,609
CO #063	Revised light fixtures	E & O	\$	3,623
CO #064	Revised door frames in Buildings 1A/1B	E & O	\$	49,841
CO #065	Remove coat hooks and lower cameras throughout buildings	E & O	\$	1,037
CO #066	Revise security device heights	E & O	\$	2,147
CO #067	Reroute water line	FC	\$	7,245
CO #068	Additional labor and materials for revised door frames in Buildings 1A/1B	E & O	\$	141,233
CO #069	Revised windows in Building 2	E & O	\$	88,611
CO #070	Revised window glazing on non-detention frames	E & O	\$	53,662
CO #071	Revised mechanical system roof access	E & O	\$	119,478
CO #072	Revised mechanical system roof access	E & O	\$	98,565
CO #073	Added room signage	SC	\$	12,781
CO #074	Revisions to detention doors and windows in Buildings 4, 5 and 6	E & O	\$	78,640
CO #075	Revised mechanical system roof access	E & O	\$	84,527
CO #076	Extended fire water line tie in	FC	\$	5,386
CO #077	French Drain at Natividad CMU Wall	SC	\$	1,449
CO #078	Added electrical work in Building 4	E & O	\$	7,293
CO #079	Credit for fascia boards	SC	\$	(5,825
CO #080	Non-Detention Keying changes	SC	\$	44,065
CO #080	Furniture, Fixture and Equipment Additions	E & O	\$	9,656
CO #081	Added Intumescent Paint for three columns	E & O	\$ \$	
CO #082	Added bed anchors at Header Board Frames	E & O	\$ \$	12,678
				14,092
CO #084	Revisions to Building 4 pharmacy	SC	\$	10,172
CO #085	Anti-Graffiti Coating	SC	\$	14,659
CO #086	No-Climb Fence fabric	SC	\$	17,074
CO #087	Revisions to Locker Room	E & O	\$	13,847
CO #088	Added plumbing in Building 7	FC	\$	5,175
CO #089	Revised bed design in Building 7	SC	\$	36,362
CO #090	Replace electrical power feeders in Building 7	FC	\$	13,292
CO #091	Repair and servicing of existing 12kV and 5kV Switchgear	FC	\$	45,174
CO #092	Delete all HVAC condensate line piping insulation	SC	\$	(3,010
CO #093	Mobilization for electrical utility shutdown 12/15/2018	FC	\$	14,304
CO #094	Add sink, plumbing, countertop	SC	\$	7,539
CO #095	Revised classroom ceiling in Buildings 2 and 6	E & O	\$	84,594
CO #096	Revisions to site security fence.	SC	\$	83,993
CO #097	Revised window glazing in Buildings 1A/1B and 2	E & O	\$	13,239
CO #098	Furniture design revisions	E & O	\$	28,992
CO #099	Negotiated resolution for Contractor claiim.	Other	\$	-
CO #100	Revise door hardware in Building 4	E & O	\$	2,547
CO #101	Relocate youth telephones in Buildings 1A/1B	E & O	\$	12,476
CO #102	Replace existing sewer pipe in Building 7	FC	\$	7,702
CO #103	Install drywall cover pipe conduit Bldg 7	SC	\$	4,326
CO #104	Revised fire sprinkler system in Building 4 lobby, visitation	SC	\$	61,220
CO #105	Revised fire sprinkler system in Building 4 rooms 152 and 163	SC	\$	11,819
CO #106	Credit: Revised mechanical system roof access	SC	\$	(82,637
CO #107	Credit for lack of circuit breaker	E & O	\$	(1,252
CO #108	Added detention grade glass in Buildings 4, 5, and 6	E & O	\$	192,728
CO #109	Revisions to Building 4 corridors	SC	\$	18,114
CO #110	Revised countertop heights throughout facility	SC	\$	41,494
CO #111	Revised bed design in Building 7	SC	\$	23,824
CO #112	Fire water check valve	FC	\$	149,645
CO #113	Revise each Gym Overhead Coiling Door to include a manual	SC	\$	7,531
CO #113		30	Ą	7,551
CO #114	operator with a removable crank.  Raise bottom of doors to 8" above slab elevation.	FC	\$	4,409
CO #114 CO #115		E & O		
	Rooms 159 & 160 – Add special coatings SC-1 and SC-2 in the shower areas.  Add Acoustical Tile Ceilings in Rooms 108, 117, 131, 132, 135	SC E & U	\$ \$	9,422 45,000
CO #11c	Ann Armisirai me cellinus in Kooms IIIX 117 131 137 135	<b>N</b>		45 00
CO #116 CO #117	Add Flooring at Officer Stations and add Podiums	SC	\$	5,419

60 11440				
CO #119	Provide and install three additional access doors	E & O	\$	1,232
CO #120	RM 115 - Provide and install Stainless Steel Posts for Toilet	SC	\$	3,893
	Partitions			
CO #121	RM 101, 148, 149 – Delete SC-1 Coating from floor and add	SC	\$	(1,136)
	replace with Concrete Sealer			
CO #122	RM 115 & 117- Provide and install recessed toilet paper holders in	SC	\$	2,165
	compliance with ADA Standards.			
CO #123	Add SC-2 Floor Coating System.	SC	\$	1,050
CO #124	Added double check valves	SC	\$	54,091
CO #125	Revisions to volume damper controls	Other	\$	66,611
CO #126	Added back draft dampers	Other	\$	20,906
CO #127	Rooms 131 & 132 – Delete card reader devices.	SC	\$	(3,091
CO #128	Room 106 – Delete all data and power outlets. REFERENCE SE1.7.1 &E2.7.1	SC	\$	(9,061
CO #129	Install Exterior Lighting Control circuits from LP-7-A-15 via lighting control panel LCP-7	Other	\$	3,677
CO #130	Revise Bed Layout and add bed headerboard (Includes the addition of a finished wood	SC	\$	13,500
	cap on wall)			
CO #131	Install additional duplex GFCI outlet in the Staff restrooms	SC	\$	5,009
CO #132	Install detention toilet paper holder in the Youth restrooms and sleeping rooms.	SC	\$	9,034
CO #139	Install flush control valves for detention plumbing fixtures in Buildings 1A/1B	SC	\$	66,432
CO #155	Remove the existing sealant at all exterior vertical masonry joints and replace with	SC	\$	-
	Security Sealant.			
CO #199	Credit for revised bioswale work	SC	\$	(7,253
CO #202	Add detention grade privacy curtains	SC	\$	1,019
CO #203	Revised window design due to fire rating	E & O	\$	5,977
2 ROS Annro	val 2019-06-25		\$	102,887
CO #133	Revision to Cell Diffuser Grilles	Other	\$	24,524
CO #136	Remove unstable soil from staff parking lot	Other	\$	11,334
CO #137	Apply Intumescent Fireproofing at Steel Saddle supporting the GLU-LAM Beams.	Other	\$	7,000
CO #138	Gym -Provide electrical raceway only for Owner Provided Wireless Access equipment at	SC	\$	922
	two locations.	50	Ψ	322
CO #140	Provide nightstands adjacent to beds.	SC	\$	23,816
		-		
CO #141	Add return air ductwork and register.	SC		5.125
	Add return air ductwork and register.  Install sewer cleanout hooks	SC SC	\$	
CO #142	Install sewer cleanout hooks	SC	\$ \$	18,655
CO #142 CO #144			\$	18,655 8,050
CO #142 CO #144 CO #145	Install sewer cleanout hooks Revise ADA toilet seats Revise security fence to add anti-climb man-gates	SC Other	\$ \$ \$ \$	18,655 8,050 3,456
CO #142 CO #144 CO #145 2. BOS Appro	Install sewer cleanout hooks Revise ADA toilet seats Revise security fence to add anti-climb man-gates val 2019-07-23	SC Other SC	\$ \$ \$ \$	18,655 8,050 3,456 <b>575,252</b>
CO #142 CO #144 CO #145 2. BOS Appro CO #134	Install sewer cleanout hooks Revise ADA toilet seats Revise security fence to add anti-climb man-gates  val 2019-07-23 Phase 1 - Glazing Installation costs Only.	SC Other SC Other	\$ \$ \$ \$	18,655 8,050 3,456 <b>575,252</b> 149,863
CO #142 CO #144 CO #145 2. BOS Appro CO #134 CO #135	Install sewer cleanout hooks Revise ADA toilet seats Revise security fence to add anti-climb man-gates  val 2019-07-23 Phase 1 - Glazing Installation costs Only. Phase 1 - Add Interior Glazing Stops to Frames.	SC Other SC Other Other	\$ \$ \$ \$ \$	18,655 8,050 3,456 <b>575,252</b> 149,863 149,861
CO #142 CO #144 CO #145 2. BOS Appro CO #134 CO #135 CO #143	Install sewer cleanout hooks Revise ADA toilet seats Revise security fence to add anti-climb man-gates  val 2019-07-23 Phase 1 - Glazing Installation costs Only. Phase 1 - Add Interior Glazing Stops to Frames. Replace faucets with anti-ligature bubblers	SC Other SC Other Other	\$ \$ \$ <b>\$</b> \$	18,655 8,050 3,456 <b>575,252</b> 149,863 149,861 4,434
CO #142 CO #144 CO #145 2. BOS Appro CO #134 CO #135 CO #143	Install sewer cleanout hooks Revise ADA toilet seats Revise security fence to add anti-climb man-gates  val 2019-07-23 Phase 1 - Glazing Installation costs Only. Phase 1 - Add Interior Glazing Stops to Frames. Replace faucets with anti-ligature bubblers Revise wall to full height to bottom of roof in Building 4	SC Other SC Other Other Other	\$ \$ \$ \$ \$ \$	18,655 8,050 3,456 <b>575,252</b> 149,863 149,861 4,434 4,500
CO #142 CO #144 CO #145 2. BOS Appro CO #134 CO #135 CO #143 CO #146 CO #147	Install sewer cleanout hooks Revise ADA toilet seats Revise security fence to add anti-climb man-gates  val 2019-07-23 Phase 1 - Glazing Installation costs Only. Phase 1 - Add Interior Glazing Stops to Frames. Replace faucets with anti-ligature bubblers Revise wall to full height to bottom of roof in Building 4 Revise accessdoor size	SC Other SC Other Other Other Other Other	\$ \$ \$ <b>\$</b> \$ \$ \$	18,655 8,050 3,456 <b>575,252</b> 149,863 149,861 4,434 4,500 2,358
CO #142 CO #144 CO #145 2. BOS Appro CO #134 CO #135 CO #143 CO #146 CO #147	Install sewer cleanout hooks Revise ADA toilet seats Revise security fence to add anti-climb man-gates  val 2019-07-23 Phase 1 - Glazing Installation costs Only. Phase 1 - Add Interior Glazing Stops to Frames. Replace faucets with anti-ligature bubblers Revise wall to full height to bottom of roof in Building 4 Revise accessdoor size Delete angle iron requirement at storefront doors	SC Other SC Other Other Other Other Other Other Other	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	18,655 8,050 3,456 <b>575,252</b> 149,863 149,861 4,434 4,500 2,358 (321
CO #142 CO #144 CO #145 2. BOS Appro CO #134 CO #135 CO #143 CO #146 CO #147 CO #148	Install sewer cleanout hooks Revise ADA toilet seats Revise security fence to add anti-climb man-gates  val 2019-07-23 Phase 1 - Glazing Installation costs Only. Phase 1 - Add Interior Glazing Stops to Frames. Replace faucets with anti-ligature bubblers Revise wall to full height to bottom of roof in Building 4 Revise accessdoor size Delete angle iron requirement at storefront doors Install concertina coil barbed wire around youth housing rec yards	SC Other SC Other Other Other Other Other Other Other SC	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	18,655 8,050 3,456 <b>575,252</b> 149,863 149,861 4,434 4,500 2,358 (321 38,349
CO #142 CO #144 CO #145 2. BOS Appro CO #134 CO #135 CO #143 CO #146 CO #147 CO #148 CO #149 CO #150	Install sewer cleanout hooks Revise ADA toilet seats Revise security fence to add anti-climb man-gates  val 2019-07-23 Phase 1 - Glazing Installation costs Only. Phase 1 - Add Interior Glazing Stops to Frames. Replace faucets with anti-ligature bubblers Revise wall to full height to bottom of roof in Building 4 Revise accessdoor size Delete angle iron requirement at storefront doors Install concertina coil barbed wire around youth housing rec yards Add fire alarm tamper switches	Other	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	18,655 8,050 3,456 <b>575,252</b> 149,863 149,861 4,434 4,500 2,358 (321 38,349 27,305
CO #142 CO #144 CO #145  2. BOS Appro CO #134 CO #135 CO #143 CO #146 CO #147 CO #148 CO #149 CO #150 CO #151	Install sewer cleanout hooks Revise ADA toilet seats Revise security fence to add anti-climb man-gates  val 2019-07-23 Phase 1 - Glazing Installation costs Only. Phase 1 - Add Interior Glazing Stops to Frames. Replace faucets with anti-ligature bubblers Revise wall to full height to bottom of roof in Building 4 Revise accessdoor size Delete angle iron requirement at storefront doors Install concertina coil barbed wire around youth housing rec yards Add fire alarm tamper switches Add data jacks throughout classroom	Other E & O	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	18,655 8,050 3,456 <b>575,252</b> 149,863 149,861 4,434 4,500 2,358 (321 38,349 27,305 8,120
CO #142 CO #144 CO #145  2. BOS Appro CO #134 CO #135 CO #143 CO #146 CO #147 CO #148 CO #149 CO #150 CO #151 CO #152	Install sewer cleanout hooks Revise ADA toilet seats Revise security fence to add anti-climb man-gates  val 2019-07-23  Phase 1 - Glazing Installation costs Only. Phase 1 - Add Interior Glazing Stops to Frames. Replace faucets with anti-ligature bubblers Revise wall to full height to bottom of roof in Building 4 Revise accessdoor size Delete angle iron requirement at storefront doors Install concertina coil barbed wire around youth housing rec yards Add fire alarm tamper switches Add data jacks throughout classroom Revisions to razor wire between buildings	SC Other SC Other Other Other Other Other Other SC Other E & O SC	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	18,655 8,050 3,456 <b>575,252</b> 149,863 149,861 4,434 4,500 2,358 (321 38,349 27,305 8,120 7,745
CO #142 CO #144 CO #145  2. BOS Appro CO #134 CO #135 CO #143 CO #146 CO #147 CO #148 CO #149 CO #150 CO #151 CO #152 CO #153	Install sewer cleanout hooks Revise ADA toilet seats Revise security fence to add anti-climb man-gates  val 2019-07-23 Phase 1 - Glazing Installation costs Only. Phase 1 - Add Interior Glazing Stops to Frames. Replace faucets with anti-ligature bubblers Revise wall to full height to bottom of roof in Building 4 Revise accessdoor size Delete angle iron requirement at storefront doors Install concertina coil barbed wire around youth housing rec yards Add fire alarm tamper switches Add data jacks throughout classroom Revisions to razor wire between buildings Floor preparation for installation of clear concrete sealer.	Other Other Other Other Other Other Other Other SC Other E & O SC Other	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	18,655 8,050 3,456 575,252 149,863 149,861 4,434 4,500 2,358 (321 38,349 27,305 8,120 7,745 4,094
CO #142 CO #144 CO #145  2. BOS Appro CO #134 CO #135 CO #143 CO #146 CO #147 CO #148 CO #149 CO #150 CO #151 CO #152 CO #153 CO #154	Install sewer cleanout hooks Revise ADA toilet seats Revise security fence to add anti-climb man-gates  val 2019-07-23 Phase 1 - Glazing Installation costs Only. Phase 1 - Add Interior Glazing Stops to Frames. Replace faucets with anti-ligature bubblers Revise wall to full height to bottom of roof in Building 4 Revise accessdoor size Delete angle iron requirement at storefront doors Install concertina coil barbed wire around youth housing rec yards Add fire alarm tamper switches Add data jacks throughout classroom Revisions to razor wire between buildings Floor preparation for installation of clear concrete sealer. Furnish and install concrete bases to mount the lockers.	SC Other SC Other Other Other Other Other SC Other E & O SC Other Other	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	18,655 8,050 3,456 575,252 149,863 149,861 4,434 4,500 2,358 (321 38,349 27,305 8,120 7,745 4,094 9,211
CO #142 CO #144 CO #145  2. BOS Appro CO #134 CO #135 CO #143 CO #146 CO #147 CO #148 CO #149 CO #150 CO #151 CO #152 CO #153 CO #154 CO #156	Install sewer cleanout hooks Revise ADA toilet seats Revise security fence to add anti-climb man-gates  val 2019-07-23  Phase 1 - Glazing Installation costs Only. Phase 1 - Add Interior Glazing Stops to Frames. Replace faucets with anti-ligature bubblers Revise wall to full height to bottom of roof in Building 4 Revise accessdoor size Delete angle iron requirement at storefront doors Install concertina coil barbed wire around youth housing rec yards Add fire alarm tamper switches Add data jacks throughout classroom Revisions to razor wire between buildings Floor preparation for installation of clear concrete sealer. Furnish and install concrete bases to mount the lockers. Add securoty exhaust grills in all youth restrooms	SC Other SC Other Other Other Other Other SC Other E & O SC Other Other SC Other SC Other SC Other SC Other	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	18,655 8,050 3,456 575,252 149,863 149,861 4,434 4,500 2,358 (321 38,349 27,305 8,120 7,745 4,094 9,211 7,900
CO #142 CO #144 CO #145  2. BOS Appro CO #134 CO #135 CO #143 CO #146 CO #147 CO #148 CO #149 CO #150 CO #151 CO #152 CO #153 CO #154 CO #156 CO #156	Install sewer cleanout hooks Revise ADA toilet seats Revise security fence to add anti-climb man-gates  val 2019-07-23 Phase 1 - Glazing Installation costs Only. Phase 1 - Add Interior Glazing Stops to Frames. Replace faucets with anti-ligature bubblers Revise wall to full height to bottom of roof in Building 4 Revise accessdoor size Delete angle iron requirement at storefront doors Install concertina coil barbed wire around youth housing rec yards Add fire alarm tamper switches Add data jacks throughout classroom Revisions to razor wire between buildings Floor preparation for installation of clear concrete sealer. Furnish and install concrete bases to mount the lockers. Add securoty exhaust grills in all youth restrooms Add fire retardant to officer work stations	SC Other SC Other Other Other Other Other SC Other E & O SC Other Other SC SC Other SC Other SC Other	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	18,655 8,050 3,456 575,252 149,863 149,861 4,434 4,500 2,358 (321 38,349 27,305 8,120 7,745 4,094 9,211 7,900 11,230
CO #142 CO #144 CO #145  2. BOS Appro CO #134 CO #135 CO #143 CO #146 CO #147 CO #148 CO #149 CO #150 CO #151 CO #152 CO #153 CO #154 CO #156 CO #158 CO #161	Install sewer cleanout hooks Revise ADA toilet seats Revise security fence to add anti-climb man-gates  val 2019-07-23  Phase 1 - Glazing Installation costs Only. Phase 1 - Add Interior Glazing Stops to Frames. Replace faucets with anti-ligature bubblers Revise wall to full height to bottom of roof in Building 4 Revise accessdoor size Delete angle iron requirement at storefront doors Install concertina coil barbed wire around youth housing rec yards Add fire alarm tamper switches Add data jacks throughout classroom Revisions to razor wire between buildings Floor preparation for installation of clear concrete sealer. Furnish and install concrete bases to mount the lockers. Add securoty exhaust grills in all youth restrooms	SC Other SC Other Other Other Other Other SC Other E & O SC Other Other SC Other SC Other SC Other SC Other	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	18,655 8,050 3,456 575,252 149,863 149,861 4,434 4,500 2,358 (321 38,349 27,305 8,120 7,745 4,094 9,211 7,900 11,230 103,685
CO #142 CO #144 CO #145  2. BOS Appro CO #134 CO #135 CO #143 CO #146 CO #147 CO #148 CO #149 CO #150 CO #151 CO #152 CO #153 CO #154 CO #156 CO #158 CO #161 CO #205	Install sewer cleanout hooks Revise ADA toilet seats Revise security fence to add anti-climb man-gates  val 2019-07-23  Phase 1 - Glazing Installation costs Only. Phase 1 - Add Interior Glazing Stops to Frames. Replace faucets with anti-ligature bubblers Revise wall to full height to bottom of roof in Building 4 Revise accessdoor size Delete angle iron requirement at storefront doors Install concertina coil barbed wire around youth housing rec yards Add fire alarm tamper switches Add data jacks throughout classroom Revisions to razor wire between buildings Floor preparation for installation of clear concrete sealer. Furnish and install concrete bases to mount the lockers. Add securoty exhaust grills in all youth restrooms Add fire retardant to officer work stations Add epoxy floor coating to rooms in Buildings 1A/1B Add polished floors in Building 6	SC Other SC Other Other Other Other Other SC Other E & O SC Other Other SC SC SC SC	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	18,655 8,050 3,456 <b>575,252</b> 149,863 149,861 4,434 4,500 2,358 (321 38,349 27,305 8,120 7,745 4,094 9,211 7,900 11,230 103,685 46,919
CO #134 CO #135 CO #143 CO #146 CO #147 CO #148 CO #149 CO #150 CO #151 CO #152 CO #153 CO #154 CO #156 CO #158 CO #161 CO #205	Install sewer cleanout hooks Revise ADA toilet seats Revise security fence to add anti-climb man-gates  val 2019-07-23 Phase 1 - Glazing Installation costs Only. Phase 1 - Add Interior Glazing Stops to Frames. Replace faucets with anti-ligature bubblers Revise wall to full height to bottom of roof in Building 4 Revise accessdoor size Delete angle iron requirement at storefront doors Install concertina coil barbed wire around youth housing rec yards Add fire alarm tamper switches Add data jacks throughout classroom Revisions to razor wire between buildings Floor preparation for installation of clear concrete sealer. Furnish and install concrete bases to mount the lockers. Add securoty exhaust grills in all youth restrooms Add fire retardant to officer work stations Add epoxy floor coating to rooms in Buildings 1A/1B	SC Other SC Other Other Other Other Other SC Other E & O SC Other Other SC SC SC SC	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	5,129 18,655 8,050 3,456  575,252 149,863 149,861 4,434 4,500 2,358 (321 38,349 27,305 8,120 7,745 4,094 9,211 7,900 11,230 103,685 46,919  695,484 4,561

CO #160	Add condensate drain line	Other	\$	1,448
CO #162	Revise light fixtures to high security recessed lights	Other	\$	10,294
CO #163	Revised sink designs	E & O	\$	532
CO #164	Relocate soap dispensers per ADA	E & O	\$	1,480
CO #165	Extend HVAC duct work	SC	\$	2,364
CO #166	Revised door lever design	SC	\$	274
CO #167	Add stainless steel toekick plates in Building 4	SC	\$	2,774
CO #168	Replace padlocks in Building 4 lockers	SC	\$	1,395
CO #169	Reshape bioswale to accomidate exterior fence pathway	SC	\$	32,447
CO #170	Revised door hardware	E & O	\$	497
CO #171	CSFM field inspection revisions	SC	\$	36,268
	•			
CO #172	Revised pathway to provide electrical room access	SC	\$	5,696
CO #173	Add metal stud frame wall in Building 4	SC	\$	2,834
CO #174	Revise door escurity glazing and hardware in Building 7	Other	\$	10,237
CO #175	Change exterior wall paint color	SC	\$	7,444
CO #176	Relocate electrical boxes	Other	\$	33,652
CO #177	Replacement electrical panels for medium voltage cables	Other	\$	39,907
CO #178	Add time clock for exterior lighting	FC	\$	2,975
CO #179	Add electrical power to room 159 in Building 4	E & O	\$	1,181
CO #180	Add carpet tile in Buildings 1A/1B	SC	\$	4,357
CO #181	Credit for deleted duct liner insulation	Other	\$	(4,242)
CO #182	Credit for revised work on Building 7	SC	\$	(803)
CO #183	Add fireproofing to beam extensions	Other	\$	2,000
CO #184	Add standard bathroom faucet	E & O	\$	421
CO #185	Construct privacy screen mockups	SC	\$	1,370
CO #186	Add ADA compliant concrete walkway	SC	\$	18,636
CO #187	Revised irrigation system	SC	\$	60,552
CO #188	Revised exterior sign and lettering	SC	\$	5,408
CO #189	Concrete wall work related to exterior sign revisions	SC	\$	11,230
CO #191	Security bars mockup	SC	\$	2,154
CO #191	Unused change order amount credit	Other	\$	(43,479)
CO #193	Modift officer station due to conflict with fire alarm panel	FC		1,831
		FC	\$	-
CO #194	Patch and repair missing fire protection material	SC	\$	2,741
CO #195	Relocate fire hydrant bollards		\$	1,761
CO #196	revised landscape and irrigation systems	SC	\$	57,226
CO #197	Add power outlets to officer stations	SC	\$	1,849
CO #198	Replace door strikes for monitoring system	Other	\$	4,994
CO #200	Install revised irrigation plan	SC	\$	28,664
CO #201	Add dig defence barrier	SC	\$	3,000
CO #211	Additional labor for dig defense barrier installation	SC	\$	5,788
CO #217	Add fence around staff parking	SC	\$	261,001
CO #220	Change intermediate security fencing to no climb fabric	Other	\$	62,718
CO #231	RFI #862 Building # 5 Added Lighting Control Device room #107	E & O	\$	3,472
2. BOS Approva			\$	729,173
CO # Pending	Dig defence barrier for Phase II	SC	\$	20,000
CO #204	CSFM field inspection revisions	SC	\$	12,274
CO #206	Revise basketball hoop design	SC	\$	16,700
CO #208	Revised air condition system	SC	\$	20,107
CO #210	Add irrigation system in courtyard	SC	\$	13,126
CO #212	Revised head of wall construction	Other	\$	100,466
CO #214	Added privacy screens in sleeping rooms	Other	\$	96,023
CO #215	Revised security glazing to meet fire rating requirements	Other	\$	3,004
CO #21C	Add fire smoke dampers	E & O	\$	24,415
CO #216	•	Other		22,401
CO #216 CO #218	Replace peremiter fence privacy fabric	Other	5	
CO #218	Replace peremiter fence privacy fabric  Add intermediate security fence between gym and Buildings 1A/1B		\$ \$	
CO #218 CO #219	Add intermediate security fence between gym and Buildings 1A/1B	Other	\$	98,472
CO #218 CO #219 CO #221	Add intermediate security fence between gym and Buildings 1A/1B  Add security cameras	Other SC	\$ \$	98,472 25,549
CO #218 CO #219 CO #221 CO #222	Add intermediate security fence between gym and Buildings 1A/1B Add security cameras Add security monitor/TV data cabling	Other SC Other	\$ \$ \$	98,472 25,549 14,930
CO #218 CO #219 CO #221 CO #222 CO #223	Add intermediate security fence between gym and Buildings 1A/1B Add security cameras Add security monitor/TV data cabling Revise drain design in peremiter fence walkway	Other SC Other Other	\$ \$ \$ \$	98,472 25,549 14,930 948
CO #218 CO #219 CO #221 CO #222	Add intermediate security fence between gym and Buildings 1A/1B Add security cameras Add security monitor/TV data cabling	Other SC Other	\$ \$ \$	98,472 25,549 14,930

CO #226	Added flush control valves for toilet units in Building 2	SC	\$	88,208
CO #227	Added conduit for wireless access points	SC	\$	6,877
CO #228	Add privacy film in doors, change security locks throughout project	SC	\$	11,933
2. BOS Pending	g Approval 2020-06-09		\$	1,116,199
CO # Pending	Add privacy panel and stainless steel column at Building 7 - Room #115.	TBD	\$	8,000
	Repair Concrete Pavers (Phase II)	TBD	\$	14,562
	Revise Classroom Door Lockset	TBD	\$	1,589
	Add secure cleanouts to proposed downspouts.	TBD	\$	4,296
	Building 7 - Engineering Judgements for Ceiling	TBD	\$	2,806
	Building 7 - Added Fire Protection to Meet T-Rating - Room #111	TBD	\$	5,632
	CSFM Replace Two Non Fire-Rated Window Glazing in Bldg. 1A/B	TBD	\$	18,462
	Add Door Position Switch at doors with electrical strike.	TBD	\$	2,300
	Add concrete stoops at Electrical Rooms	TBD	\$	7,074
	Add concrete stoops at Gym	TBD	\$	4,824
	Global Settlement for CRs 239, 242, 247, 248, 271, 273, 308, 328	TBD	\$	141,560
CO #230	Paint exposed head of wall	SC	\$	1,326
CO #232	11/7/19 - Building 6 - Delete speciality outlet and floor box requirement. MCOE	Other	\$	(13,655
	confirmed the outlets are not needed. (credit)			` '
CO #233	Change lockset hardware at building 7	SC	\$	1,625
CO #234	Provide four (4) California Engineering Judgement Stamps	Other	\$	2,590
CO #235	Added Sprinkler Coverage at Building 4 Control Room Windows	E & O	\$	28,051
CO #236	CSFM requiremens for Glue Laminate Beam at head of wall.	Other	\$	3,190
CO #237	Staff Parking - Revise Irrigation due to fence layout	FC	\$	2,404
CO #238	Fire Alarm System Program Revisions - 24/7 Monitoring	SC	\$	10,737
CO #239	Repair of finished landscape.	Other	\$	1,625
CO #240	Misc. Changes to Address BSCC Requirements as Detailed in RFI 940	SC	\$	34,382
CO #241	BSCC Privacy Screen Modifications	SC	\$	25,507
CO #242	Privacy Film for Building 2 Windows per BSCC	SC	\$	25,114
CO #243	Add Bollard Near Fire Post Indicator Valve	TBD	\$	2,495
CO #246	Wall Sealant for Buildings 1A/B, 4, 6 (Address Water Intrusion)	Other	\$	299,025
CO #247	Repair Concrete Pavers (Phase I)	TBD	\$	86,919
CO #248-A	Exhaust Fan Revisions and Duct Silencers - Utility Reconfiguration (1 of 2)	TBD	\$	74,813
CO #251-A	Erosion Control Measures due to roof watershed (excludes EVA Road) ASI 99 (Phase I - Only 1 CR)	TBD	\$	230,081
CO# 244	Replace strobe in youth restrooms to meet CSFM/BSCC requirements	SC	\$	7,671
CO# 245	Roof Drainage Diverters at Building 4	SC	, \$	1,023
CO#248-B	Exhaust Fan Revisions and Duct Silencers - Materials (2 of 2)	TBD	\$	80,175
2. Funded by C	Change Order Savings		\$	136,550
CO #060	Partially Settled Amount for Time Impact Analyss #2	FC	\$	125,873
CO #207	Revised color scheme mockups	SC	\$	583
CO #209	Install light security shrouds in rec yard	SC	\$	14,292
CO #213	Credit for irrigation piping size difference	Other	\$	(5,401
CO #229	Paint accent wall in Building 4 photography area	SC	\$	1,203
rand Total			\$	7,610,343

