

This page intentionally left blank.



KEY CONSIDERATIONS

- Sallyport entry location maintains original San Mateo MHRC location. Clients will have visibility to incoming visitors and new clients from the east bedrooms. Entry and Meditation areas are adjusted to maximize corridor space upon entering through the Sallyport.
- Staff Work Area size is maximized with new arrangement of Kitchenette in the Staff Lounge. Staff have full visibility throughout the MHRC with centralized work area location.
- Optional staff only access door added directly into

 Exam/Consult for medication distribution. New Medication
 Room location includes a walk up window for client distribution if desired.
- Kitchenette has been moved to Staff Lounge Room instead of previous corridor location. Egress only door through Staff Lounge is maintained.
- Daylight openings are maximized in staff offices located on front face of the building. Staff have better site visibility offering additional security of site.
- Building services components have been enlarged per MEP requirements and can have optional exterior doors for direct access.
- Housekeeping is directly accessible in staff corridor, maximizing Dining/Activity and Nourishment areas. Storage Room is accessed directly from Nourishment Room.
- Clothing Sterilization is removed from each MHRC and planned for placement in the MHRC Support Building. Area is given back to staff program.
- Laundry will be a staff only area, clients in this facility are not expected to perform laundry services as part of their treatment program.
- New Staff Offices enhance visibility within client bedroom wings and offer closer access to the courtyards.
- Building geometry is simplified for ease of construction and potential cost savings.





CANVONDESIGN

KEY CONSIDERATIONS

- Waiting / Reception area is reduced. Conference Room is directly accessed from main entry and maximizes daylight opportunities.
- Open Work area has been reduced in size and can be used for visiting clinicians or staff training needs.
- Staff Lounge has been combined with Security Lounge as one large, communal space.
- Dietary Director's Office is directly adjacent to Kitchen and has natural daylight facing the Main Entry.
- Kitchen location is directly accessible from the Receiving Entry / Loading Zone.
- Staff toilets have been right sized to include private showers and changing areas within each room.
- Clothing sterilization room is removed from each MHRC and provided within Support Building for staff use as needed.
- Electrical ductbank routing proposed with an alternative option if the switchboard is located inside of the building.











