



Medical Staff/ Administration



NATIVIDAD MEDICAL
CENTER


1441 Constitution Blvd, Salinas, CA 93912

SECOND FLOOR
BUILDING
KEY PLAN




This Building's Seismic Performance Rating

Structural Integrity



Equipment and Systems
Critical to Patient Care



The State of California has determined that the hospital building is at risk of not being functional to provide care to its patients or the community after an earthquake.


More info:




Facility Number: 17353
Building Number: BLD- 02542

This Building's Seismic Performance Rating

Structural Integrity



Equipment and Systems
Critical to Patient Care



The State of California has determined that the hospital building is at risk of not being functional to provide care to its patients or the community after an earthquake.


More info:




Facility Number: 17353
Building Number: BLD- 02544

This Building's Seismic Performance Rating

Structural Integrity



Equipment and Systems
Critical to Patient Care



The State of California has determined that the hospital building is at risk of not being functional to provide care to its patients or the community after an earthquake.


More info:




Facility Number: 17353
Building Number: BLD- 02545

This Building's Seismic Performance Rating

Structural Integrity



Equipment and Systems
Critical to Patient Care



The State of California has determined that the hospital building is at risk of not being functional to provide care to its patients or the community after an earthquake.


More info:




Facility Number: 17353
Building Number: BLD- 03827

This Building's Seismic Performance Rating

Structural Integrity



Equipment and Systems
Critical to Patient Care



The State of California has determined that the hospital building is at risk of not being functional to provide care to its patients or the community after an earthquake.


More info:




Facility Number: 17353
Building Number: BLD- 03828

This Building's Seismic Performance Rating

Structural Integrity



Equipment and Systems
Critical to Patient Care



The State of California has determined that this building does not significantly jeopardize life, but may not be repairable or functional following an earthquake.


More info:




Facility Number: 17353
Building Number: BLD- 03862

This Building's Seismic Performance Rating

Structural Integrity



Equipment and Systems
Critical to Patient Care



The State of California has determined that the hospital building is at risk of not being functional to provide care to its patients or the community after an earthquake.

More info:



Facility Number: 17353
Building Number: BLD- 05986