## Exhibit 1

## Natividad Medical Center's Emergency Entrance Door Replacement

## **Background/ Current Situation**

Building 500 is occupied by the Emergency Department, Radiology Department and Admitting. There are two automatic entrance doors allowing access to these departments and provide patient access to the Emergency Department and Admitting. These doors also serve as an entrance for NMC staff. The entrance is comprised of an outer door which is a bi-folding automatic door and an interior door which is a pair of automatic swing doors. The Bi-fold doors have been out of operation for two years. Their failure was caused by exposure of high wind pressure, preventing the doors from opening and causing an actuator failure. The double swing automatic doors, although still functional, have also been a casualty of the exposure of high wind pressure. The Emergency Department has requested to have the automatic doors replaced with automatic sliding doors.

The scope of work would include:

- Remove and Dispose of 1 bi-fold automatic Doors
- Remove and Dispose of 1 Swing automatic Doors
- Install 2 new sliding automatic Doors

## **Key Milestones:**

- January 31, 2011 Architect drafted construction documents
- February 9, 2011- OSHPD to approved construction document
- January, 2012 Board Authorize to go out for Public Bid
- January, 2012 Advertise for Tenant Improvement
- March, 2012 Deemed bidder non responsive
- August, 2012 Board Authorize to go out for Public Rebid
- November, 2012 Board Authorize to Award Contract
- December, 2012 Notice to Start Construction
- February, 2013 Construction completion

