


Exhibit C

This page intentionally left blank.

Exhibit C. Site Photographs



Photograph 1. View of the staking and flagging of the entrance from Brookdale Drive and Carmel Valley Road. Repeated below with black line at staking top.





Photograph 2. View of staking and flagging looking directly into proposed entrance from Carmel Valley Road north edge (at intersection with Brookdale Drive).



Photograph 3. View of graded area east of proposed entrance design. Depressions have been excavated to begin the drainage site improvements approved with the Phase 1 final map.



Photograph 4. View looking east at northern edge of Carmel Valley Road showing the staking and flagging for the retaining wall at highest points of landform that is proposed to contain the guard kiosk. Repeated below with white line at staking top.

