Facilities and Construction 1441 Constitution Boulevard PO Box 81611 Salinas, CA 93912-1611 Phone 831-755-4220 Fax 831-755-4268



### **Contractor Evaluation**

Date: March 28, 201	8
Contractor:	OTTO Construction
Contract #:	NMC 2016-01
Job Order Number:	JN06-09-JC1616-00
Job Order Title:	Mental Health Unit (MHU) Refree
Project Mamager:	Brian Griffin

				Total Weighted
S.No.	Description	Value(1-4)	Weight(1-4)	Score
1	Proposal submitted on time (1 wk<\$125,000, 2 wks >\$125 to <\$500, or in agreed time) (Yes - 4, No -1)	3	2	6
2	Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1)	4	3	12
3	Proposal revisions submitted within three days (Yes - 4, No - 1)	1	2	2
4	Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)	3	2	6
5	Construction started on time (Yes - 4, No - 1)	4	2	8
6	Construction completed on time (Yes - 4, No - 1)	4	4	16
7	Project close out documents completed w/in 30 days of Substantial Completion (Yes - 4, No - 1)	4	2	8
8	Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	2	3	6
9	Superintendent Performance (Excellent - 4, Good -3, Satisfactory -2, Poor -1)	3	4	12
10	% of Job Order using Local Subcontractors (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
11	% of Job Order using Small Local Businesses (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
12	% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
13	Supplimental Job Orders dont exceed initial JO by > 5% (1% - 4, >2% - 3, >3% - 2, >4% - 1)	4	4	16
14	Demonstrated conscientious safety awareness (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	1	3	3
			Total Score:	143
		Maximum Pose	sible Total Score:	172
		Per	formance Rating:	83.14%

Facilities and Construction 1441 Constitution Boulevard PO Box 81611 Salinas, CA 93912-1611 Phone 831-755-4220 Fax 831-755-4268



### **Contractor Evaluation**

Date: January 03, 20	)18
Contractor:	OTTO Construction
Contract #:	NMC 2016-01
Job Order Number:	JN06-17-JC1627-00
Job Order Title:	Building 940 - Mental Health Rei
Project Mamager:	Brian Griffin

S.No.	Description	Value(1-4)	Weight(1-4)	Total Weighted Score
1	Proposal submitted on time (1 wk<\$125,000, 2 wks >\$125 to <\$500, or in agreed time) (Yes - 4, No -1)	4	2	8
2	Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1)	4	3	12
3	Proposal revisions submitted within three days (Yes - 4, No - 1)	4	2	8
4	Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)	4	2	8
5	Construction started on time (Yes - 4, No - 1)	4	2	8
6	Construction completed on time (Yes - 4, No - 1)	4	4	16
7	Project close out documents completed w/in 30 days of Substantial Completion (Yes - 4, No - 1)	4	2	8
8	Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	3	3	9
9	Superintendent Performance (Excellent - 4, Good -3, Satisfactory -2, Poor -1)	4	4	16
10	% of Job Order using Local Subcontractors (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
11	% of Job Order using Small Local Businesses (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
12	% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
13	Supplimental Job Orders dont exceed initial JO by > 5% (1% - 4, >2% - 3, >3% - 2, >4% - 1)	4	4	16
14	Demonstrated conscientious safety awareness (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
			Total Score:	169
		Maximum Poss	sible Total Score:	172
		Per	formance Rating:	98.26%

# **Contractor Evaluation**

## **Job Order Contract**

Date: March 28, 2018

Contractor:	Ausonio
Contract #:	NMC 2016-02
Job Order Number:	JN07-21-JC1629-00
Job Order Title:	Mechoshade Installation Bldg 30
Project Mamager:	Brian Griffin

				Total Weighted
S.No.	Description	Value(1-4)	Weight(1-4)	Score
1	Proposal submitted on time (1 wk<\$125,000, 2 wks >\$125 to <\$500, or in agreed time) (Yes - 4, No -1)	1	2	2
2	Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1)	4	3	12
3	Proposal revisions submitted within three days (Yes - 4, No - 1)	4	2	8
4	Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)	4	2	8
5	Construction started on time (Yes - 4, No - 1)	4	2	8
6	Construction completed on time (Yes - 4, No - 1)	1	4	4
7	Project close out documents completed w/in 30 days of Substantial Completion (Yes - 4, No - 1)	1	2	2
8	Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
9	Superintendent Performance (Excellent - 4, Good -3, Satisfactory -2, Poor -1)	3	4	12
10	% of Job Order using Local Subcontractors (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	3	4	12
11	% of Job Order using Small Local Businesses (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
12	% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
13	Supplimental Job Orders dont exceed initial JO by > 5% (1% - 4, >2% - 3, >3% - 2, >4% - 1)	4	4	16
14	Demonstrated conscientious safety awareness (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
			Total Score:	140
		Maximum Pos	sible Total Score:	172
		Per	formance Rating:	81.40%

Facilities and Construction 1441 Constitution Boulevard PO Box 81611 Salinas, CA 93912-1611 Phone 831-755-4220 Fax 831-755-4268



### **Contractor Evaluation**

Date: June 13, 2018	
Contractor:	Ausonio
Contract #:	NMC 2016-02
Job Order Number:	JN07-22-JC1631-00
Job Order Title:	Elevator Protective Film
Project Mamager:	Brian Griffin

				Total Weighted
S.No.	Description	Value(1-4)	Weight(1-4)	Score
1	Proposal submitted on time (1 wk<\$125,000, 2 wks >\$125 to <\$500, or in agreed time) (Yes - 4, No -1)	1	2	2
2	Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1)	4	3	12
3	Proposal revisions submitted within three days (Yes - 4, No - 1)	4	2	8
4	Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)	4	2	8
5	Construction started on time (Yes - 4, No - 1)	1	2	2
6	Construction completed on time (Yes - 4, No - 1)	4	4	16
7	Project close out documents completed w/in 30 days of Substantial Completion (Yes - 4, No - 1)	4	2	8
8	Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	3	3	9
9	Superintendent Performance (Excellent - 4, Good -3, Satisfactory -2, Poor -1)	4	4	16
10	% of Job Order using Local Subcontractors (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
11	% of Job Order using Small Local Businesses (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
12	% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
13	Supplimental Job Orders dont exceed initial JO by > 5% (1% - 4, >2% - 3, >3% - 2, >4% - 1)	4	4	16
14	Demonstrated conscientious safety awareness (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
			Total Score:	157
		Maximum Poss	ible Total Score:	172
		Perf	ormance Rating:	91.28%

Facilities and Construction 1441 Constitution Boulevard PO Box 81611 Salinas, CA 93912-1611 Phone 831-755-4220 Fax 831-755-4268



**Job Order Contract** 

### **Contractor Evaluation**

Date: March 28, 2018

Contractor:	Ausonio
Contract #:	NMC 2016-02
Job Order Number:	JN07-25-JC1633-00
Job Order Title:	Compactor Drain
Project Mamager:	Brian Griffin

				Total Weighted
S.No.	Description	Value(1-4)	Weight(1-4)	Score
1	Proposal submitted on time (1 wk<\$125,000, 2 wks >\$125 to <\$500, or in agreed time) (Yes - 4, No -1)	1	2	2
2	Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1)	4	3	12
3	Proposal revisions submitted within three days (Yes - 4, No - 1)	4	2	8
4	Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)	4	2	8
5	Construction started on time (Yes - 4, No - 1)	4	2	8
6	Construction completed on time (Yes - 4, No - 1)	4	4	16
7	Project close out documents completed w/in 30 days of Substantial Completion (Yes - 4, No - 1)	4	2	8
8	Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	3	3	9
9	Superintendent Performance (Excellent - 4, Good -3, Satisfactory -2, Poor -1)	4	4	16
10	% of Job Order using Local Subcontractors (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
11	% of Job Order using Small Local Businesses (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
12	% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
13	Supplimental Job Orders dont exceed initial JO by > 5% (1% - 4, >2% - 3, >3% - 2, >4% - 1)	4	4	16
14	Demonstrated conscientious safety awareness (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	3	3	9
			Total Score:	160
		Maximum Poss	ible Total Score:	172
		Perf	ormance Rating:	93.02%

Facilities and Construction 1441 Constitution Boulevard PO Box 81611 Salinas, CA 93912-1611 Phone 831-755-4220 Fax 831-755-4268



### **Contractor Evaluation**

Date: June 13, 2018	
Contractor:	Ausonio
Contract #:	NMC 2017-01
Job Order Number:	JN08-01-JC1702-00
Job Order Title:	Monument Sign Installation
Project Mamager:	Brian Griffin

				Total Weighted
S.No.	Description	Value(1-4)	Weight(1-4)	Score
1	Proposal submitted on time (1 wk<\$125,000, 2 wks >\$125 to <\$500, or in agreed time) (Yes - 4, No -1)	3	2	6
2	Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1)	4	3	12
3	Proposal revisions submitted within three days (Yes - 4, No - 1)	1	2	2
4	Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)	4	2	8
5	Construction started on time (Yes - 4, No - 1)	4	2	8
6	Construction completed on time (Yes - 4, No - 1)	4	4	16
7	Project close out documents completed w/in 30 days of Substantial Completion (Yes - 4, No - 1)	4	2	8
8	Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	2	3	6
9	Superintendent Performance (Excellent - 4, Good -3, Satisfactory -2, Poor -1)	3	4	12
10	% of Job Order using Local Subcontractors (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
11	% of Job Order using Small Local Businesses(>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
12	% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
13	Supplimental Job Orders dont exceed initial JO by > 5% (1% - 4, >2% - 3, >3% - 2, >4% - 1)	4	4	16
14	Demonstrated conscientious safety awareness (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
			Total Score:	154
		Maximum Poss	sible Total Score:	172
		Per	ormance Rating:	89.53%