

Exhibit D

This page intentionally left blank.



HOUSING AND COMMUNITY DEVELOPMENT

[Announcements](#)

[Development Services](#)

[Planning
Services](#)

[Permit Center](#)

[GIS / Maps](#)

[About Us](#)



Vacation Rental Home Inspection Checklist

Property Information

Vacation Rental Address and Unit/Suite/Apt # 1273 Lisbon Ln, Pebble Beach CA 93953

Total number of bedrooms 4

Total number of onsite parking spaces (e.g. garage, driveway) 4 + 2 Car Garage

Interior Inspection

Beds are located in approved Bedrooms, in compliance with the Building Code at the time of construction, with appropriate ingress and egress.

Every sleeping room has a functional smoke alarm.

Every hallway with a sleeping room has a functional smoke alarm. Every floor has a functional carbon monoxide alarm.

All built-in kitchen appliances operate properly and space for food storage, preparation, and serving are in good and safe condition. All electrical outlets in kitchen and bathrooms are Ground Fault Circuit Interrupter (GFCI) protected.

Water heater is properly strapped, adequately vented, and temperature and pressure relief valves are drained to outside.

Other heating equipment is in safe operating condition and placed in an approved location.

There is at least one readily accessible class A fire extinguisher located in the home that has been serviced annually by a certified fire extinguisher company.

The building conforms to the applicable state building and fire codes at the time the building was constructed.

Exterior Inspection

There is no evidence of infestation, garbage, and debris at the site.

The property has active garbage pick-up service.

If a garage is present, it is only used as a garage and only non-combustible flooring exists. Driveway, if present, is open and accessible to vehicles.

Property is in an overall safe and sanitary condition.

Water heater is properly strapped, adequately vented, and temperature and valves are drained to outside. Other heating equipment is in safe operating condition and placed in an approved location.

Home Inspection Results

Passed

Failed

Remarks/Observations:

Excellent Condition

Home Inspector Certification


Under penalty of perjury, the undersigned certifies that the information on this form is based on an actual site inspection of the property and is complete and accurate.

Home Inspector or General Contractor Name & Acknowledgement: Dave Bigham, CCI - Pro View Property Inspection

- California Contractors State License Board License Classification Type B
- California Contractors State License Board License Classification Type B-2
- California Contractors State License Board License Classification Type C-47
- California Real Estate Inspection Association # 155461
- American Society of Home Inspectors # 259301
- International Code Council
- International Association of Certified Home Inspectors

Please check the relevant certification agency and write your License/Certification number below:

Date: January 22, 2016



Click 'Print' at the top of this page and save as a PDF.

1441 Schilling Place

South 2nd Floor

Salinas, CA 93901

831-755-5025

[Sitemap](#)

[Contact Us](#)

