

Job Order Contract

Contractor:	Newton Construction & Management, Inc.
Contract #:	NMC - 2022-03
Job Order Number:	JN19-05-JC2215-00
Job Order Title:	Emergency Domestic Hot Water
Project Mamager:	Brian Griffin

0.11-	Description			Total Weighted
S.No.	Description	Value(1-4)	Weight(1-4)	Score
1	Proposal submitted on time (1 wk<\$125,000, 2 wks >\$125 to < \$500, or in agreed time) (Yes - 4, No -1)	4	2	8
2	Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1)	4	3	12
3	Proposal revisions submitted within three days (Yes - 4, No - 1)	4	2	8
4	Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)	4	2	8
5	Construction started on time (Yes - 4, No - 1)	4	2	8
6	Construction completed on time (Yes - 4, No - 1)	4	4	16
7	Project close out documents completed w/in 30 days of Substantial Completion (Yes - 4, No - 1)	4	2	8
8	Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
9	Superintendent Performance (Excellent - 4, Good -3, Satisfactory -2, Poor -1)	4	4	16
10	% of Job Order using Local Subcontractors (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
11	% of Job Order using Small Local Businesses (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
12	% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
13	Supplimental Job Orders dont exceed initial JO by > 5% (1% - 4, >2% - 3, >3% - 2, >4% - 1)	4	4	16
14	Demonstrated conscientious safety awareness (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
			Total Score:	172
		Maximum Pos	sible Total Score:	172
		Per	formance Rating:	100.00%
			diroo i tuting.	100.0070



Job Order Contract

Contractor:	Newton Construction & Management, Inc.
Contract #:	NMC - 2022-03
Job Order Number:	JN19-05-JC2215-00
Job Order Title:	Emergency Domestic Hot Water
Project Mamager:	Brian Griffin

				Total Weighted
S.No.	Description	Value(1-4)	Weight(1-4)	Score
1	Proposal submitted on time (1 wk<\$125,000, 2 wks >\$125 to < \$500, or in agreed time) (Yes - 4, No -1)	4	2	8
2	Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1)	4	3	12
3	Proposal revisions submitted within three days (Yes - 4, No - 1)	4	2	8
4	Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)	4	2	8
5	Construction started on time (Yes - 4, No - 1)	4	2	8
6	Construction completed on time (Yes - 4, No - 1)	4	4	16
7	Project close out documents completed w/in 30 days of Substantial Completion (Yes - 4, No - 1)	4	2	8
8	Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
9	Superintendent Performance (Excellent - 4, Good -3, Satisfactory -2, Poor -1)	4	4	16
10	% of Job Order using Local Subcontractors (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
11	% of Job Order using Small Local Businesses (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
12	% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
13	Supplimental Job Orders dont exceed initial JO by > 5% (1% - 4, >2% - 3, >3% - 2, >4% - 1)	4	4	16
14	Demonstrated conscientious safety awareness (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
			Total Score:	172
		Maximum Pose	sible Total Score:	172
		Per	ormance Rating:	100.00%



Job Order Contract

Date: July 30, 2024

Contractor:	Staples Construction Company Inc.
Contract #:	NMC - 2023-01
Job Order Number:	JN20-06-JC2311-00
Job Order Title:	MHU - Emergency Door Replacement, Bldg 940
Project Manager:	Brian Griffin

				Total Weighted
S.No.	Description	Value(1-4)	Weight(1-4)	Score
1	Proposal submitted on time (1 wk<\$125,000, 2 wks >\$125 to < \$500, or in agreed time) (Yes - 4, No -1)	3	2	6
2	Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1)	4	3	12
3	Proposal revisions submitted within three days (Yes - 4, No - 1)	4	2	8
4	Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)	4	2	8
5	Construction started on time (Yes - 4, No - 1)	4	2	8
6	Construction completed on time (Yes - 4, No - 1)	4	4	16
7	Project close out documents completed w/in 30 days of Substantial Completion (Yes - 4, No - 1)	4	2	8
8	Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
9	Superintendent Performance (Excellent - 4, Good -3, Satisfactory -2, Poor -1)	4	4	16
10	% of Job Order using Local Subcontractors (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
11	% of Job Order using Small Local Businesses (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
12	% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
13	Supplimental Job Orders dont exceed initial JO by > 5% (1% - 4, >2% - 3, >3% - 2, >4% - 1)	4	4	16
14	Demonstrated conscientious safety awareness (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
			Total Score:	170
		Maximum Pos	sible Total Score:	172
		Per	formance Rating:	98.84%



Job Order Contract

Total

Date: July 30, 2024	
Contractor:	Staples Construction Company Inc.
Contract #:	NMC - 2023-01
Job Order Number:	JN20-07-JC2312-00
Job Order Title:	Skytron light installation OR 5
Project Manager:	Brian Griffin

				Total Weighted
S.No.	Description	Value(1-4)	Weight(1-4)	Score
1	Proposal submitted on time (1 wk<\$125,000, 2 wks >\$125 to < \$500, or in agreed time) (Yes - 4, No -1)	3	2	6
2	Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1)	4	3	12
3	Proposal revisions submitted within three days (Yes - 4, No - 1)	4	2	8
4	Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)	3	2	6
5	Construction started on time (Yes - 4, No - 1)	4	2	8
6	Construction completed on time (Yes - 4, No - 1)	4	4	16
7	Project close out documents completed w/in 30 days of Substantial Completion (Yes - 4, No - 1)	4	2	8
8	Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
9	Superintendent Performance (Excellent - 4, Good -3, Satisfactory -2, Poor -1)	4	4	16
10	% of Job Order using Local Subcontractors (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
11	% of Job Order using Small Local Businesses (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
12	% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
13	Supplimental Job Orders dont exceed initial JO by > 5% (1% - 4, >2% - 3, >3% - 2, >4% - 1)	4	4	16
14	Demonstrated conscientious safety awareness (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
			Total Score:	168
		Maximum Pos	sible Total Score:	172
		Peri	formance Rating:	97.67%



Job Order Contract

- - -

Date: July 30, 2024

Contractor:	Staples Construction Company Inc.
Contract #:	NMC - 2023-01
Job Order Number:	JN20-07-JC2312-01
Job Order Title:	Skytron light installation OR 5 Supplemental 1 - Chiller 1 Rebuild-Central Plant float work
Project Manager:	Brian Griffin

S.No.	Description			Total Weighted Score
5.NO.	Description	Value(1-4)	Weight(1-4)	Score
1	Proposal submitted on time (1 wk<\$125,000, 2 wks >\$125 to < \$500, or in agreed time) (Yes - 4, No -1)	3	2	6
2	Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1)	4	3	12
3	Proposal revisions submitted within three days (Yes - 4, No - 1)	4	2	8
4	Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)	3	2	6
5	Construction started on time (Yes - 4, No - 1)	4	2	8
6	Construction completed on time (Yes - 4, No - 1)	4	4	16
7	Project close out documents completed w/in 30 days of Substantial Completion (Yes - 4, No - 1)	4	2	8
8	Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
9	Superintendent Performance (Excellent - 4, Good -3, Satisfactory -2, Poor -1)	4	4	16
10	% of Job Order using Local Subcontractors (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
11	% of Job Order using Small Local Businesses (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
12	% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
13	Supplimental Job Orders dont exceed initial JO by > 5% (1% - 4, >2% - 3, >3% - 2, >4% - 1)	4	4	16
14	Demonstrated conscientious safety awareness (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
			Total Score:	168
		Maximum Pos	sible Total Score:	172
		Per	formance Rating:	97.67%



Job Order Contract

Date: July 30, 2024

Contractor:	Staples Construction Company Inc.
Contract #:	NMC - 2023-01
Job Order Number:	JN20-05-JC2313-00
Job Order Title:	On Call Physician Room Electrical, Bldg 500, 3rd Floor, ICU
Project Manager:	Brian Griffin

			Total Weighted
Description	Value(1-4)	Weight(1-4)	Score
Proposal submitted on time (1 wk<\$125,000, 2 wks >\$125 to < \$500, or in agreed time) (Yes - 4, No -1)	3	2	6
Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1)	4	3	12
Proposal revisions submitted within three days (Yes - 4, No - 1)	4	2	8
Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)	4	2	8
Construction started on time (Yes - 4, No - 1)	4	2	8
Construction completed on time (Yes - 4, No - 1)	4	4	16
Project close out documents completed w/in 30 days of Substantial Completion (Yes - 4, No - 1)	4	2	8
Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
Superintendent Performance (Excellent - 4, Good -3, Satisfactory -2, Poor -1)	4	4	16
% of Job Order using Local Subcontractors (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
% of Job Order using Small Local Businesses (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
Supplimental Job Orders dont exceed initial JO by > 5% (1% - 4, >2% - 3, >3% - 2, >4% - 1)	4	4	16
Demonstrated conscientious safety awareness (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
		Total Score:	170
	Maximum Pos	sible Total Score:	172
	Per	ormance Rating:	98.84%
	\$500, or in agreed time) (Yes - 4, No -1) Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1) Proposal revisions submitted within three days (Yes - 4, No - 1) Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1) Construction started on time (Yes - 4, No - 1) Construction completed on time (Yes - 4, No - 1) Project close out documents completed w/in 30 days of Substantial Completion (Yes - 4, No - 1) Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1) Superintendent Performance (Excellent - 4, Good - 3, Satisfactory -2, Poor -1) % of Job Order using Local Subcontractors (>70% - 4, >60% - 3, >50% - 2, >40% - 1) % of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1) Supplimental Job Orders dont exceed initial JO by > 5% (1% - 4, >2% - 3, >3% - 2, >4% - 1) Demonstrated conscientious safety awareness (Excellent - 4,	Proposal submitted on time (1 wk<\$125,000, 2 wks >\$125 to < \$500, or in agreed time) (Yes - 4, No - 1)3Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1)4Proposal revisions submitted within three days (Yes - 4, No - 1)4Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)4Construction started on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)4Construction started on time (Yes - 4, No - 1)4Construction completed on time (Yes - 4, No - 1)4Project close out documents completed w/in 30 days of Substantial Completion (Yes - 4, No - 1)4Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)4Superintendent Performance (Excellent - 4, Good -3, Satisfactory -2, Poor -1)4% of Job Order using Local Subcontractors (>70% - 4, >60% - 3, >50% - 2, >40% - 1)4% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)4% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)4Demonstrated conscientious safety awareness (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)4	Proposal submitted on time (1 wk<\$125,000, 2 wks >\$125 to < \$500, or in agreed time) (Yes - 4, No - 1)3Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1)43Proposal revisions submitted within three days (Yes - 4, No - 1)42Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)42Construction started on time (Yes - 4, No - 1)42Construction completed on time (Yes - 4, No - 1)42Construction completed on time (Yes - 4, No - 1)42Quality of construction (Yes - 4, No - 1)42Quality of construction (Yes - 4, No - 1)42Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)44Superintendent Performance (Excellent - 4, Good -3, Satisfactory - 2, Poor -1)44% of Job Order using Small Local Businesses (>70% - 4, >60% - - 3, >50% - 2, >40% - 1)44% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)44Supplimental Job Orders dont exceed initial JO by > 5% (1% - 4, >2% - 3, >3% - 2, >4% - 1)43Demonstrated conscientious safety awareness (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)43



Job Order Contract

_ . .

Date:

Contractor:	Staples Construction Company Inc.
Contract #:	NMC - 2023-01
Job Order Number:	JN20-08-JC2315-00
Job Order Title:	Room 301 Air Balance Repairs,
Project Manager:	Brian Griffin

				Total Weighted
S.No.	Description	Value(1-4)	Weight(1-4)	Score
1	Proposal submitted on time (1 wk<\$125,000, 2 wks >\$125 to < \$500, or in agreed time) (Yes - 4, No -1)	4	2	8
2	Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1)	4	3	12
3	Proposal revisions submitted within three days (Yes - 4, No - 1)	4	2	8
4	Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)	4	2	8
5	Construction started on time (Yes - 4, No - 1)	4	2	8
6	Construction completed on time (Yes - 4, No - 1)	4	4	16
7	Project close out documents completed w/in 30 days of Substantial Completion (Yes - 4, No - 1)	4	2	8
8	Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
9	Superintendent Performance (Excellent - 4, Good -3, Satisfactory -2, Poor -1)	4	4	16
10	% of Job Order using Local Subcontractors (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
11	% of Job Order using Small Local Businesses (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
12	% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
13	Supplimental Job Orders dont exceed initial JO by > 5% (1% - 4, >2% - 3, >3% - 2, >4% - 1)	4	4	16
14	Demonstrated conscientious safety awareness (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
			Total Score:	172
		Maximum Pos	sible Total Score:	172
		Per	formance Rating:	100.00%
			5	



Job Order Contract

Contractor:	Staples Construction Company Inc.
Contract #:	NMC - 2023-01
Job Order Number:	JN20-09-JC2316-00
Job Order Title:	Emergency Medical Air Dryer $R\epsilon$
Project Manager:	Brian Griffin

				Total Weighted
S.No.	Description	Value(1-4)	Weight(1-4)	Score
1	Proposal submitted on time (1 wk<\$125,000, 2 wks >\$125 to < \$500, or in agreed time) (Yes - 4, No -1)	4	2	8
2	Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1)	4	3	12
3	Proposal revisions submitted within three days (Yes - 4, No - 1)	4	2	8
4	Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)	4	2	8
5	Construction started on time (Yes - 4, No - 1)	4	2	8
6	Construction completed on time (Yes - 4, No - 1)	4	4	16
7	Project close out documents completed w/in 30 days of Substantial Completion (Yes - 4, No - 1)	4	2	8
8	Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
9	Superintendent Performance (Excellent - 4, Good -3, Satisfactory -2, Poor -1)	4	4	16
10	% of Job Order using Local Subcontractors (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
11	% of Job Order using Small Local Businesses (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
12	% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
13	Supplimental Job Orders dont exceed initial JO by > 5% (1% - 4, >2% - 3, >3% - 2, >4% - 1)	4	4	16
14	Demonstrated conscientious safety awareness (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
			Total Score:	172
		Maximum Pos	sible Total Score:	172
		Per	formance Rating:	100.00%
		1 01	anoo raang.	100.0070



Job Order Contract

Date: July 30, 2024	
Contractor:	Staples Construction Company Inc.
Contract #:	NMC - 2023-01
Job Order Number:	JN20-11-JC2318-00
Job Order Title:	Roof top Safety Rail, Bldg. 500 F
Project Manager:	Brian Griffin

S No.	Description	Volue(1_1)		Total Weighted
S.No.	Description	Value(1-4)	Weight(1-4)	Score
1	Proposal submitted on time (1 wk<\$125,000, 2 wks >\$125 to < \$500, or in agreed time) (Yes - 4, No -1)	4	2	8
2	Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1)	4	3	12
3	Proposal revisions submitted within three days (Yes - 4, No - 1)	4	2	8
4	Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)	4	2	8
5	Construction started on time (Yes - 4, No - 1)	4	2	8
6	Construction completed on time (Yes - 4, No - 1)	4	4	16
7	Project close out documents completed w/in 30 days of Substantial Completion (Yes - 4, No - 1)	4	2	8
8	Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
9	Superintendent Performance (Excellent - 4, Good -3, Satisfactory -2, Poor -1)	4	4	16
10	% of Job Order using Local Subcontractors (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
11	% of Job Order using Small Local Businesses (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
12	% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
13	Supplimental Job Orders dont exceed initial JO by > 5% (1% - 4, >2% - 3, >3% - 2, >4% - 1)	4	4	16
14	Demonstrated conscientious safety awareness (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
			Total Score:	172
		Maximum Pose	sible Total Score:	172
		Perf	ormance Rating:	100.00%



Job Order Contract

Date: July 30, 2024	
Contractor:	Staples Construction Company Inc.
Contract #:	NMC - 2023-01
Job Order Number:	JN20-12-JC2320-00
Job Order Title:	Emergency ARU Entrance Door
Project Manager:	Brian Griffin

S.No.	Description	Value(1-4)		Total Weighted Score
			Weight(1-4)	
1	Proposal submitted on time (1 wk<\$125,000, 2 wks >\$125 to < \$500, or in agreed time) (Yes - 4, No -1)	4	2	8
2	Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1)	4	3	12
3	Proposal revisions submitted within three days (Yes - 4, No - 1)	4	2	8
4	Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)	4	2	8
5	Construction started on time (Yes - 4, No - 1)	4	2	8
6	Construction completed on time (Yes - 4, No - 1)	4	4	16
7	Project close out documents completed w/in 30 days of Substantial Completion (Yes - 4, No - 1)	4	2	8
8	Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
9	Superintendent Performance (Excellent - 4, Good -3, Satisfactory -2, Poor -1)	4	4	16
10	% of Job Order using Local Subcontractors (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
11	% of Job Order using Small Local Businesses (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
12	% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
13	Supplimental Job Orders dont exceed initial JO by > 5% (1% - 4, >2% - 3, >3% - 2, >4% - 1)	4	4	16
14	Demonstrated conscientious safety awareness (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
			Total Score:	172
		Maximum Poss	sible Total Score:	172
		Perf	ormance Rating:	100.00%



Job Order Contract

Contractor:	Staples Construction Company Inc.
Contract #:	NMC - 2023-01
Job Order Number:	JN20-14-JC2326-00
Job Order Title:	Prunedale Retaining Wall repair
Project Manager:	Brian Griffin

S.No.	Description	Value(1-4)	Weight(1-4)	Total Weighted Score
1	Proposal submitted on time (1 wk<\$125,000, 2 wks >\$125 to < \$500, or in agreed time) (Yes - 4, No -1)	4	2	8
2	Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1)	4	3	12
3	Proposal revisions submitted within three days (Yes - 4, No - 1)	4	2	8
4	Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)	4	2	8
5	Construction started on time (Yes - 4, No - 1)	4	2	8
6	Construction completed on time (Yes - 4, No - 1)	4	4	16
7	Project close out documents completed w/in 30 days of Substantial Completion (Yes - 4, No - 1)	4	2	8
8	Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
9	Superintendent Performance (Excellent - 4, Good -3, Satisfactory -2, Poor -1)	4	4	16
10	% of Job Order using Local Subcontractors (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
11	% of Job Order using Small Local Businesses (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
12	% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
13	Supplimental Job Orders dont exceed initial JO by > 5% (1% - 4, >2% - 3, >3% - 2, >4% - 1)	4	4	16
14	Demonstrated conscientious safety awareness (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
			Total Score:	172
		Maximum Pos	sible Total Score:	172
		Per	formance Rating:	100.00%



Job Order Contract

Total

Date: July 30, 2024

Contractor:	Staples Construction Company
Contract #:	NMC - 2023-01
Job Order Number:	JN20-15-JC2327-00
Job Order Title:	Sanborn Clinic Sink
Project Manager:	Brian Griffin

0.11-	Beenvietten			Total Weighted
S.No.	Description	Value(1-4)	Weight(1-4)	Score
1	Proposal submitted on time (1 wk<\$125,000, 2 wks >\$125 to < \$500, or in agreed time) (Yes - 4, No -1)	4	2	8
2	Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1)	4	3	12
3	Proposal revisions submitted within three days (Yes - 4, No - 1)	4	2	8
4	Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)	4	2	8
5	Construction started on time (Yes - 4, No - 1)	4	2	8
6	Construction completed on time (Yes - 4, No - 1)	4	4	16
7	Project close out documents completed w/in 30 days of Substantial Completion (Yes - 4, No - 1)	4	2	8
8	Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
9	Superintendent Performance (Excellent - 4, Good -3, Satisfactory -2, Poor -1)	4	4	16
10	% of Job Order using Local Subcontractors (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
11	% of Job Order using Small Local Businesses (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
12	% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
13	Supplimental Job Orders dont exceed initial JO by > 5% (1% - 4, >2% - 3, >3% - 2, >4% - 1)	4	4	16
14	Demonstrated conscientious safety awareness (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
			Total Score:	172
		Maximum Pos	sible Total Score:	172
		Per	formance Rating:	100.00%

Inc.



Job Order Contract

Date: November 07, 2024

Contractor:Staples Construction Company Inc.Contract #:NMC - 2023-01Job Order Number:JN20-13-JC2323-00Job Order Title:Emergency Shower Pan Repair Emergency Shower Pan Repair Rm. 316, 331 and 332, Bldg 500Rm. 316, Bldg 500Project Manager:Brian Griffin

				Total Weighted
S.No.	Description	Value(1-4)	Weight(1-4)	Score
1	Proposal submitted on time (1 wk<\$125,000, 2 wks >\$125 to < \$500, or in agreed time) (Yes - 4, No -1)	4	2	8
2	Initial proposal was accurate per Scope with only minor revisions required (Yes - 4, No - 1)	4	3	12
3	Proposal revisions submitted within three days (Yes - 4, No - 1)	4	2	8
4	Submittals submitted on time (90% - 4, 80% - 3, 70% - 2, 60% - 1)	4	2	8
5	Construction started on time (Yes - 4, No - 1)	4	2	8
6	Construction completed on time (Yes - 4, No - 1)	4	4	16
7	Project close out documents completed w/in 30 days of Substantial Completion (Yes - 4, No - 1)	4	2	8
8	Quality of construction (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
9	Superintendent Performance (Excellent - 4, Good -3, Satisfactory -2, Poor -1)	4	4	16
10	% of Job Order using Local Subcontractors (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
11	% of Job Order using Small Local Businesses (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
12	% of Local Hire (>70% - 4, >60% - 3, >50% - 2, >40% - 1)	4	4	16
13	Supplimental Job Orders dont exceed initial JO by > 5% (1% - 4, >2% - 3, >3% - 2, >4% - 1)	4	4	16
14	Demonstrated conscientious safety awareness (Excellent - 4, Good - 3, Satisfactory - 2, Poor - 1)	4	3	12
			Total Score:	172
		Maximum Poss	sible Total Score:	172
		Perf	ormance Rating:	100.00%