







Medical Staff/ Administration





NATIVIDAD MEDICAL
CENTER



1441 Constitution Blvd, Salinas, CA 93912

THIRD FLOOR BUILDING KEY PLAN




Building - 05986

Signage Location




This Building's Seismic Performance Rating

Structural Integrity



Equipment and Systems
Critical to Patient Care



The State of California has determined that the hospital building is at risk of not being functional to provide care to its patients or the community after an earthquake.


More info:




Facility Number:
Building Number: BLD-

This Building's Seismic Performance Rating

Structural Integrity



Equipment and Systems
Critical to Patient Care



The State of California has determined that the hospital building is at risk of not being functional to provide care to its patients or the community after an earthquake.


More info:




Facility Number:
Building Number: BLD-

This Building's Seismic Performance Rating

Structural Integrity



Equipment and Systems
Critical to Patient Care



The State of California has determined that the hospital building is at risk of not being functional to provide care to its patients or the community after an earthquake.


More info:




Facility Number:
Building Number: BLD-

This Building's Seismic Performance Rating

Structural Integrity



Equipment and Systems
Critical to Patient Care



The State of California has determined that the hospital building is at risk of not being functional to provide care to its patients or the community after an earthquake.


More info:




Facility Number:
Building Number: BLD-

This Building's Seismic Performance Rating

Structural Integrity



Equipment and Systems
Critical to Patient Care



The State of California has determined that the hospital building is at risk of not being functional to provide care to its patients or the community after an earthquake.


More info:




Facility Number:
Building Number: BLD-

This Building's Seismic Performance Rating

Structural Integrity



Equipment and Systems
Critical to Patient Care



The State of California has determined that this building does not significantly jeopardize life, but may not be repairable or functional following an earthquake.


More info:




Facility Number:
Building Number: BLD-

This Building's Seismic Performance Rating

Structural Integrity



Equipment and Systems
Critical to Patient Care



The State of California has determined that the hospital building is at risk of not being functional to provide care to its patients or the community after an earthquake.

More info:



Facility Number:
Building Number: BLD-